

XIN HUA WORKSHOP PTE. LTD.

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Reg : 201838521G

Vehicle Number : SLB292X
Vehicle Model : TOYOTA ALTIS
Accident Date : 01.10.2021
Original Reg Date : 11.11.2009

Date : 04.10.2021
Chassis : MR053ZEE106148607
TP Ins. CHINA TAIPING

Asher.

ESTIMATE

1	1 set	Front Bumper <i>Distorted</i>		495.00	✓
2	1 pc	Front Bumper Badge <i>new</i>		95.20	✓
3	2 pcs	Front Bumper Side Retainers <i>LH Rnd</i>	85.30	170.60	45. ✓
4	1 set	Front Bumper Clips <i>new</i>		30.00	✓
5	1 pc	Front Bumper Reinforcement <i>Dented</i>		365.00	✓
6	1 pc	Front Bumper lower grille <i>new</i>		165.80	+
7	1 pc	Front Bumper Fog Lamp LH <i>Crackd</i>		198.20	✓
8	1 pc	Front Bumper Fog Lamp Cover LH <i>Crackd</i>		82.30	✓
9	1 pc	Front grille <i>phl m</i>		328.80	+
10	1 pc	Headlamp LH <i>Crackd</i>		535.00	✓
11	1 pc	Headlamp lower bracket LH <i>new</i>		123.80	+
12	1 set	Headlamp Clips LH <i>new</i>		30.00	10. ✓
13	1 pc	Front Fender LH <i>Distorted</i>		486.20	✓
14	1 pc	Front Fender Inner Housing (Outer) <i>Regis</i>		391.30	+
15	1 pc	Front Fender Emblem VVTI LH <i>new</i>		72.20	43. ✓
16	1 pc	Front Fender Bracket LH <i>Bent</i>		65.20	✓
17	1 pc	Front Fender Inner Shield LH <i>torn</i>		165.00	✓
18	1 set	Front Fender Inner Shield Clips <i>new</i>		30.00	✓
19	1 pc	Front resonator box <i>Crackd</i>		189.20	✓
20	1 pc	Front radiator <i>2 new</i>		987.80	+
21	1 pc	Front condenser <i>1 new</i>		876.90	+
22	1 pc	Front air vent <i>2 new</i>		108.60	✓
23	1 pc	Front door Lh <i>Regis</i>		1,001.40	+
24	1 pc	Front sport rim Lh <i>Cut</i>		845.30	480/sw ✓
25	1 pc	Front Absorber <i>Bent</i>		428.60	326. ✓
26	1 pc	Front Absorber Top Mounting <i>new</i>		119.50	+
27	1 pc	Front Lower Arm <i>Bent</i>		598.60	375. ✓
28	1 pc	Front Knuckle Arm <i>Bent</i>		523.60	✓
29	1 pc	Front Wheel Bearing <i>Rnd</i>		172.50	✓
30	1 pc	Front Anti Roll Bar <i>2 new</i>		253.10	+
31	2 pcs	Front Anti Roll Bar Bush <i>new</i>	36.00	72.00	+
32	1 pc	Front Anti Roll Bar Link		125.10	+

33	1 pc	Front stabilizer linkage <i>seen</i>		145.80	+
34	1 pc	Front Drive Shaft <i>seen</i>		1,210.10	+
35	1 pc	Steering Rack and Pinion <i>seen</i>		1,328.60	+

Bonnet
Dented

98750 ✓
757

Less 25%

C/F

12,816.30

3,204.08

9,612.23

5397
3822-75

S.N 480

Special Nett

1	1 pc	Front Number Plate w/Cover <i>seen</i>		50.00	+
2	1 pc	Front Tyre LH <i>seen</i>		220.00	+

Labour charge

Panel Beating		1,800.00	900
Spray painting		1,800.00	850
Check Wiring on headlamp		120.00	30
Anti rust		180.00	50
To remove condenser and top up gas		120.00	x.
Remove and install front undercarriage.		180.00	✓
To perform computerize wheel alignment.		120.00	80

2090

total

14,202.23

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
1/s 05/10/21.

06 days.

total: 6392.75

1/s: 5.1K.

5.1K