

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

MS China Taiping Insurance (Singapore) Pte Ltd
Date: 06/10/2021
Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO: SLK7463B
CHASSIS NO : NHP1707060333
MAKE / MODEL : Toyota Sienta HYBRID 1.5X CVT
DATE OF ACCIDENT: 30/09/2021
YOUR INSURED VEHICLE NUMBER: YN4541J
MILEAGE: 53398 km

	<u>PARTS DISCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>	
1	F/L fender DD	1PC	\$ 924.00	\$ 924.00	654 -
2	F/L fender inner liner MIS	1PC	\$ 234.00	\$ 234.00	-
3	Front headlamp (LH) BR	1PC	\$ 990.00	\$ 990.00	-
4	Front bumper BR	1PC	\$ 900.00	\$ 900.00	581 -
5	Front bumper LH protector MIS	1PC	\$ 238.88	\$ 238.88	189 -
6	Front bumper LH side bracket MIS	1PC	\$ 90.00	\$ 90.00	-
7	Front Bonnet DD	1PC	\$ 1,288.50	\$ 1,288.50	845 -
8	Front bonnet hinge (LH) BT	1PC	\$ 129.00	\$ 129.00	-
9	F/L door assy DD	1PC	\$ 1,610.00	\$ 1,610.00	1200 -
10	R/L taillamp X NH	1PC	\$ 550.00	\$ 550.00	-
11	R/L tailgate reflector X NH	1PC	\$ 380.00	\$ 380.00	-
12	Rear end panel X NH	1PC	\$ 828.00	\$ 828.00	-
13	Rear bumper cover DD	1PC	\$ 900.00	\$ 900.00	750 -
14	Rear bumper LH side bracket BR	1PC	\$ 105.00	\$ 105.00	-
15	Rear bumper LH seal X NH	1PC	\$ 104.40	\$ 104.40	-
16	R/L sliding door assembly DD	1PC	\$ 1,800.00	\$ 1,800.00	1295 -
17	R/L door outer rubber protector MIS	1PC	\$ 280.00	\$ 280.00	215 -
18	Rear sliding door motor LH X NH	1PC	\$ 3,200.00	\$ 3,200.00	-
19	R/L fender outer side garnish MIS	1PC	\$ 480.00	\$ 480.00	128 -
20	R/L fender X R	1PC	\$ 924.00	\$ 924.00	-
21	Front bumper reinforcement DD	1PC	\$ 380.00	\$ 380.00	-
22	Front bumper energy absorber BR	1PC	\$ 120.00	\$ 120.00	-
LIST TOTAL S\$:				\$ 16,455.78	16,455.78
25% DISCOUNT S\$:				\$ 4,113.95	-25%
				\$ 12,341.84	5928.75

SPECIAL NETT

1	Front bumper clips 11"	1 SET	\$ 80.00	30
2	Rear bumper clips 11"	1 SET	\$ 80.00	30
3	Front fender inner linear clips X NH	1 SET	\$ 80.00	-
4	Rear reverse sensor X NH	1 SET	\$ 250.00	-
5	R/L wheel cap MIS	1 SET	\$ 260.00	100 -
Special Nett Total S\$:			\$ 750.00	300 -

160 -

LABOUR CHARGES

- 1 To labour charge for removing out F/L fender, Front headlamp (LH), Front bumper, F/L and R/L door and Front bonnet out to facilitate repairs and replacement of damaged parts. \$ 1,250.00 1900
- 2 To respray F/L fender, Front bumper, Front bonnet, Front LH tyre rim, Front LH door and Rear LH door *rear bumper* \$ 1,600.00 1320
- 3 To apply rustproofing on all replacement parts \$ 100.00 30
- 4 To conduct a standard of opearting procedures post repairs scan test as a requirements upon completion of collision repairs \$ 300.00 200
- 5 To deactivate and active high voltage battery as a sfaety precautions \$ 300.00 120

LABOUR TOTAL S\$: \$ 3,550.00

TOTAL S\$: \$ 16,266.84

7% GST \$ 1,138.68

GRAND TOTAL S\$: \$ 17,405.51

2,670.00 ✓

Steve (LKK)
7/10/21, 19.30hr

ML 1L = 8758.75
L/S
My 1L My Supp-1744.68
8 dgs 10,503.43
L/S-8402.74
= 8400

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms China Taiping Insurance (Singapore) Pte Ltd

Date: 06/10/2021

Attn : MOTOR CLAIMS DEPT

ESTIMATE SUPPLEMENTARY

VEHICLE NO. SLK7463B

CHASSIS NO : NSP1707021790

MAKE / MODEL : Toyota Sienta Hybrid 1.5X CVT

DATE OF ACCIDENT: 30/09/2021

YOUR INSURED VEHICLE NUMBER: YN4541J

MILEAGE: 53398 km

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	Front grille ✓ BR	1PC	\$596.25	\$596.25 ✓ <i>pls by surgo</i>
2	Front windscreen BR	1PC	\$2,000.00	\$2,000.00 - <i>pls by surgo 1600 ✓</i>
3	F/L headlamp panel BT	1PC	\$175.00	\$175.00 - <i>pls by surgo, 130 ✓</i>
LIST TOTAL S\$:				\$2,771.25
25.00% DISCOUNT S\$:				\$692.81
				\$2,078.44

2326.25
-25%
1744.68

Parts 10,469.38
Supplementary 2,771.25
13,240.63
SN 320.00
Labor 2,670.00
16,230.63

Lump sum \$12,900.00
8 days