

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417853
ROB No: 53291793J, Tel: 6741-1730 / 731, Email: liubro@gmail.com

Invoice/Ref No: YN8202L190418

Estimate

Customer	
Name: Somp Insurance Singapore Private Limited	Date: 06-10-21
Address: Motor Claims Department	Vehicle No: YN8202L
50 Raffles Place #05-01 / 06	Model/Make: Mitsubishi
Singapore Land Tower Singapore 048623	Fuso FM65FM2RDEB

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Rh Side Guard (Safety Bar) <i>Bent</i>	\$ 800.00	SN
2	Side Guard Bracket <i>2x</i>	\$ 200.00	SN
3	Pillar Outer Aluminium Panel <i>Bent</i>	\$ 400.00	SN
4	Powergate Panel Outer <i>2x</i>	\$ 380.00	SN
5	Wooden Plank <i>CNA</i>	\$ 600.00	SN
6	Tail Lamp <i>CNA</i>	\$ 198.00	SN
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 600.00	480
	To putty & spray painting & including touch up paint on accident affected areas	\$ 200.00	100
	To apply Rust Proofing, reseat tuffcoating treatment on accident area	\$ 50.00	17x

Total Parts & Labour of estimate for damaged vehicle \$ 3,428.00

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

Not Approved
7/10/21
1/5 \$ 2000
Wheeler's After repair
3 days

1-198
252
7-14850
5-1800
1-500
252850
202
2022

LK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: