



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS3/LPC21005496/R1vf3e2-1 Date: 26/10/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 4626M	Veh. Inspected	SJL 3449M	
Policy No.	Z/21/VC10/109573	Coverage (\$)	0.00	
Claim No.	21/21/21/VC10/024533	Excess (\$)	0.00	
Assign From	KENNY LIM	Assign Date	06/10/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ISIS 1.8LX A	c.c	1794	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	ZNM100057655	Colour	BLACK	
Odometer	240903 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	WEST LAKE	5 mm	
L/H Front Tyre	195/65 R15	WEST LAKE	5 mm	
R/H Rear Tyre	195/65 R15	WEST LAKE	5 mm	
L/H Rear Tyre	195/65 R15	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/05/2021	Inspection Date	05/05/2021	
Survey held at	MAJESTY AUTOWORKS - 1 BUKIT BATOK CRESCENT #03-25			
Repairer	-			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	