

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jenny Lew

Date: 07 Oct 2021

Preliminary Advice

Vehicle No	: SKU8919G	Accident Date	: 01/10/2021
Make	: TOYOTA HARRIER	Policy No.	: DMPCSNW00156592104
Assignment Date	: 06/10/2021	Excess	: S\$750.00
Date of Inspection	: 7/10/21	Est. Duration of Repair	: 8
Inspection At	: NEXWAVE AUTO		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,310.00
Revised Amount	:S\$	6,100.00
Check Items (Estimated)	:S\$	150.00
Total	:S\$	6,250.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	64,000.00
COE / PARF Rebate	:S\$	38,738.00
Salvage Value	:S\$	
Margin for Repair	:S\$	25,262.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Vehicle repair on part by part. According to repairer, there is no 2nd parts available.

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .