

REF: CS3/CTI21010317/Duy³

ASSIGNMENT

Date:

Cost:

TP RES / DD RES / EVA / INV / MV

Vehicle No: SGQ 3445H

Work up to/s

SJZ 8935U

DMPCSNW00012362100

SNM21D205662/C2

Excess:

(Officer's Record)

Make/Model

(Point of Condition)

Remark: The veh had commenced its repair at the time of inspection.

Est. of Market Value:

IDAC Accident Report Consistent? : Yes or No

GIA / IR Seen: Consistent? : Yes or No

Est. Repair: 5 days Res.: Yes or No

Turn Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SGQ 3445H Yr Regn: 2019/July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Civic C.C. 1597

Colour: Silver A/C: Insured / Std / RI / NA

Sp. Reading: 41730 T/Radio: Insured / Std / RI / NA

Eng/No: R16B25510636

C/No: MRHFC5650KT000602

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55 R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PER / SUMI /

TOYO / YOKO or

Michelin

Front

Rear

R/Bal: 5 mm

R/Bal: 5 mm

L/Bal: 5 mm

L/Bal: 5 mm

D.O.A. 03/10/2021

D.O.I. 07/10/2021

Survey held at Bak Heng Man AMK

Des. of Damages: F/R / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action/Instruction
China Kiping

Repair range 4k to 4.5k 5 repair days

19/11/2021 Submit PRS.

Date/Time, File Pass to? : Prefl. Report

1) 19/11 TYPIS : Final Report

Date/Time, File Return to?

2)

Report Format: TP

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee: : Site Insp (\$

: Interview (\$

: Tech. Invs (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others