

ASS. REC. BY: Marcus

REF:

CS/11121010323/4+f3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLW 28134

at Workshop m/s

of

Insured:

Policy No. D20MPC0000663-01

Claims No. MPC2021D0004306

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

5 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Disorder / Jammed / Leaked / Burnt or

Brake: Disorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

14/10/24 4/5 \$5500 confirmed with David Dep 10h.

RED: 4090.35;42%

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

) \$ + RS. \$ SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$))

TOTAL

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: 3036/10/21

Your Ref:

The Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- (Subsequent modification(s) must be resurveyed and approved by the repairer)
- Final approval from Insurance Company

Date: 6th OCT 2021

The Claim's Manager
Motor Claims Dept.

INDIA INTERNATIONAL INSURANCE PTE. LTD.
64, Cecil Street, #05-00, IOB Bldg.
Singapore 049711

Acknowledged by Repairer

Name Of Insured : Ms Deng Hong

Date Of Accident : 06/10/21 (11:30hrs)

Certificate No : D20MFC0000663_01

not Allowed
here
Express @ 750
1/5#5500
the ph the my
\$ 5000

Estimate cost of repair to TOYOTA WISH (A) 1.8 MPV - SLW 2813 U

1 pc front bonnet	SUC	\$ 798.80	✓
1 pc front bonnet logo emblems	nei	66.20	✓
1 pc front bonnet lock	nei	92.60	✓
2 pcs front bonnet o/s & n/s hinge	SUC	51.10	✓
6 pcs front bonnet insulator clips	nei	4.10	✓
6 pcs front bonnet rubber clips	nei	3.90	✓
1 pc front grille (with chrome moulding)	nei	472.80	✓
6 pcs front grille clips	nei	4.20	✓
1 pc front top garnish cover	nei	81.60	✓
6 pcs front top garnish cover clips	nei	4.20	✓
1 pc front support panel	nei	1,179.40	✓
1 pc front o/s fender	nei	795.50	✓
2 pcs o/s & n/s head lamp assy (HID)	nei	1,150.10	✓
1 pc front number plate & frame	nei	60.00	✓
1 pc front bumper	nei	674.90	✓
10 pcs front bumper clips	nei	4.30	✓
1 pc front bumper damper	nei	83.50	✓
1 pc front bumper reinforcement	nei	295.30	✓
2 pcs front bumper o/s & n/s side retainer	nei	55.30	✓
1 pc front bumper centre lower air scoop grille	nei	76.80	✓
2 pcs front bumper o/s & n/s air scoop grille	nei	55.70	✓
2 pcs front bumper o/s & n/s fog lamp assy	nei	370.10	✓
2 pcs front bumper o/s & n/s fog lamp garnish	nei	75.20	✓
1 pc front centre brace panel	nei	161.10	✓
		8,333.80	✓
	Less 25%	2,083.45	✓
		\$ 6,250.35	✓

To wiring check up & adjust headlight alignment.

40.00 20

To remove, refix & refill Ra134 gas, to enable repair front support panel & head lamp panel.

150.00 100

To putty & respray painting (Pearl) on all affected parts.

1,650.00 850

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out front support panel, front o/s fender & necessary parts.

1,500.00 1000

Dollars : Nine Thousand Five Hundred Ninety And Cents
Thirty Five Only.

\$ 9,590.35

HUP MOTOR TRADING & SERVICE

65/10-6

200
4887.95

6/10/21