

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI21010326/EQY3N2**Date:** 17/11/2021**REFERENCE**

Insured/Claimant: NOR AZMIE BIN IBRAHIM Policy No: DMPCSNW00032292100

Date of Loss: 05/10/2021

Nature of Claim: OD

Claim No: SNM21D205688/C01/CHEESC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SKB7527K**

Make &amp; Model: KIA CERATO FORTE, 1.6 SX (A)

Engine No: G4FCBH355356

Reg. Date: 27/06/2011 (Man. Year: 2011)

Chassis No: KNAFW411MB5451030

Colour: Brown

Odometer: 237567 km

Engine Capacity: 1591 cc

Market Value/New Car Price: S\$37,000.00

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 215/45R17

Rear Tyre Size: 215/45R17

Front Left Side: Michelin 4 mm

Rear Left Side: Michelin 4 mm

Front Right Side: Michelin 4 mm

Rear Right Side: Michelin 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,251.45	2,973.80	1,277.65	30.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,321.68	947.86	373.82	28.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,573.13</b>	<b>3,921.66</b>	<b>1,651.47</b>	<b>29.63</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,100.00</b>		
<b>(S\$)</b>	5,573.13	3,100.00	2,473.13	44.38
<b>+ GST 7.00/7.00% (S\$)</b>	390.12	217.00	173.12	44.38
<b>Nett Amount (S\$)</b>	<b>5,963.25</b>	<b>3,317.00</b>	<b>2,646.25</b>	<b>44.38</b>

**INSPECTION**

Date of Assignment: 07/10/2021

Date Inspected: 07/10/2021 Inspected At:

BLK 1010, BUKIT MERAH LANE 3,

#01-117 S159724

REPAIRER: GOLDBELL ENGINEERING PTE LTD

Estimated Period of Repair: 7.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Nov 2021)
Parts:	143	KIA CERATO FORTE 1.6 SX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKB7527K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Total Parts		4,251.45 F	*2,973.80 F
				Total Parts (S\$)	4,251.45	2,973.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	Total of Labour	New	579.60	319.20
2	Total Paint Including Material	New	742.08	628.66
<b>Gross Labour Cost (S\$)</b>			<b>1,321.68</b>	<b>947.86</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >