

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chee So Chow

Date: 07 Oct 2021

Preliminary Advice

Vehicle No	: SKB7527K	Accident Date	: 05/10/2021
Make	: KIA CERATO FORTE	Policy No.	: DMPCSNW00032292100
Assignment Date	: 07/10/2021	Excess	: S\$0.00
Date of Inspection	: 07/10/2021	Est. Duration of Repair	: 7
Inspection At	: GOLDBELL ENGINEERING PTE LTD (TUAS) 10 TUAS AVE 18 SINGAPORE 638894		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,573.13
Revised Amount	:S\$	4,119.08
Check Items (Estimated)	:S\$	877.15
Total	:S\$	4,996.23
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	37,000.00
COE / PARF Rebate	:S\$	17,514.00
Salvage Value	:S\$	
Margin for Repair	:S\$	19,486.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Pleas note that the preliminary advice amount (Revised & Check items) stated are subject to part prices and labour cost.