



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CS/CTI21010326/Eqy3 Date: 07/10/2021 Code: CTI	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SKB 7527K
	Policy No.	DMPCSNW00032292100	Coverage (\$)	0.00
	Claim No.	SNM21D205688/C01/CHEESC	Excess (\$)	0.00
	Assign From	CHEE SO CHOW	Assign Date	07/10/2021
2. Vehicle Particulars & Condition				
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	05/10/2021	Inspection Date	07/10/2021
	Survey held at	BLK 1010, BUKIT MERAH LANE 3, #01-117 S159724		
	Repairer	GOLDBELL ENGINEERING PTE LTD		
5a. Remarks				
	A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			