

55 UBI ROAD 1, SINGAPORE 408699

TEL 6366 2323 FAX 6841 1183

EMAIL: NORA.KHALID@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0822/2021/KS
DATE	:	6-Oct-21
WIP	:	47864

VEHICLE NOT IN WORKSHOP KINDLY ARRANGE FOR SURVEY ON 6/10/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4638

OWNER'S NAME	:	MR SURESH MONGAS
ADDRESS	:	1 JALAN KUALA #21-01 SINGAPORE 239639
TELEPHONE	:	HP +65 90093122
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	7210020626
VEHICLE NO	:	SMY 3307 K
MODEL CODE	:	AUDI Q3 1.4 TFSI 5 TRONIC
MODEL YEAR	:	26/2/2021
ENGINE NO	:	CZB C23753
CHASSIS NO	:	WBAUZZ2934M1063389
RELEASE	:	
DATE IN	:	
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	6-OCT-21
PLACE OF ACCIDENT	:	550 GUILLEMARD RD. SG 599639

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMY 3307 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEDLIGHT WASHER ASSY AND FRONT PARKING, ATD	S/N \$ 480.00	/ ✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	/ ✓
3	TO RENEW AND REINSTALL AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS. (R1234)	S/N \$ 2,000.00	2 ✓ NN
4	TO REMOVE AND REINSTALL FRONT SUSPENSION ASSY WITH SUBFRAME. INSPECT FOR DAMAGES AND RENEW IF NECESSARY.	S/N \$ 2,400.00	2 ✓
5	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT.. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 4,800.00	1000 ✓
6	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND BONNET.	\$ 3,000.00	1650 ✓
7	TO RENEW RHS FRONT RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT TEST.	S/N \$ 520.00	280 ✓
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 384.00	/ ✓
TOTAL LABOUR CHARGES		: \$ 13,984.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6041 1183
EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 3307 K

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER / <i>re</i>	1	\$	1,008.00	806.4
2	FRONT BUMPER CONNECTING PIECE <i>X NN</i>	1	\$	145.00	
3	FRONT BUMPER CLOSING ELEMENT - RH <i>X NN</i>	1	\$	59.00	
4	FRONT BUMPER GRILLE - CENTER <i>X NN</i>	1	\$	217.00	
5	FRONT BUMPER GRILLE - RH <i>X NN</i>	1	\$	110.00	
6	FRONT BUMPER SPOILER / <i>cut</i>	1	\$	383.00	306.4
7	FRONT BUMPER AIR GUIDE GRILLE - RH <i>- cut</i>	1	\$	153.00	122
8	RADIATOR GRILLE <i>X</i>	1	\$	1,433.00	
9	RADIATOR GRILLE STRIKER PLATE <i>X</i>	1	\$	243.00	
10	RADIATOR GRILLE CLOSING ELEMENT <i>X</i>	1	\$	190.00	
11	FRONT BUMPER GUIDE SECTION - RH <i>- re</i>	1	\$	39.00	30.48
12	FRONT BUMPER FOAM FILLER PIECE <i>X</i>	1	\$	102.00	
13	FRONT BUMPER REINFORCEMENT BEAM <i>X</i>	1	\$	916.00	
14	FRONT BUMPER TOP COVER <i>- cut</i>	1	\$	123.00	98
15	"CAUTION" STICKER <i>-</i>	1	\$	14.00	10.88
16	"A/c" STICKER <i>-</i>	1	\$	8.00	5.68
17	SIGNAL HORN <i>X</i>	1	\$	130.00	
18	HORN BRACKET - RH <i>X</i>	1	\$	22.00	
19	FRONT PARKING AID SENSOR <i>X</i>	2		TBC	
20	FRONT PARKING AID SENSOR SEAL RING <i>X NN</i>	4	\$	14.00	
SUB TOTAL SPARE PARTS		:	\$	5,309.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 3307 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER - RH <i>— BNC</i>	1	\$ 1,286.00	1208.8
22	FRONT FENDER ATTACHMENT PARTS <i>✓ NN</i>	1	\$ 63.00	
23	FRONT FENDER BRACE - RH <i>✓ BT</i>	1	\$ 88.00	69.76
24	FRONT FENDER BRACKET - RH <i>— BT</i>	1	\$ 32.00	24.88
25	HEADLIGHT MOUNTING - RH <i>✓ BR</i>	1	\$ 118.00	94.4
26	LED HEADLIGHT - RH <i>— cat</i>	1	\$ 5,589.00	4471.2
27	LIFT CYLINDER - RH <i>✓ NN</i>	1	\$ 210.00	
28	HEADLIGHT HOSE - RH <i>X</i>	1	\$ 80.00	
29	FRONT WHEEL ARCH COVER - LH / RH <i>— cat</i>	2	\$ 536.00	428.8
30	LOCK CARRIER <i>✓ NN</i>	1	\$ 1,272.00	
31	RADIATOR COOLANT <i>✓ NN</i>	6	\$ 267.00	
32	RADIATOR AIR GUIDE - RH <i>✓ NN</i>	1	\$ 38.00	
33	RADIATOR AIR GUIDE - UPPER <i>✓ NN</i>	1	\$ 42.00	
34	OUTSIDE TEMPERATURE SENSOR BRACKET <i>✓ NN</i>	1	\$ 7.00	
35	FRONT ALUMINIUM RIM - RH <i>— cat</i>	1	\$ 1,262.00	1009.6
36	FRONT LOWER ARM - RH <i>✓ BT</i>	1	\$ 454.00	362.8
37	FRONT WHEEL HUB WITH BEARING - RH <i>✓ DM</i>	1	\$ 528.00	434.8
38	FRONT WHEEL BEARING HOUSING - RH <i>✓ DM</i>	1	\$ 668.00	534
39	FRONT LOWER ARM BALL JOINT - RH <i>✓ BT</i>	1	\$ 140.00	111.6
40	FRONT COUPLING ROD - RH <i>✓ NN</i>	1	\$ 93.00	
SUB TOTAL SPARE PARTS		:	\$ 12,773.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 3307 K.

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
41	GAS SHOCK ABSORBER - RH ☒ BT	1	\$ 306.00	244.4
42	TIE ROD - RH ☒ BT	1	\$ 87.00	69.28
43	TIE ROD END - RH ☒ BT	1	\$ 122.00	97.2
44	FRONT NO PLATE ☒ X MN	S/N	\$ 60.00	
45	SUNDRIES ☒ NEC		\$ 400.00	131.44
TOTAL SPARE PARTS		:	\$ 19,057.00	
TOTAL LABOUR CHARGES		:	\$ 13,984.00	
GRAND TOTAL		:	\$ 33,041.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Blue Q'ap
06/10/21
Not Authorised

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

5 Days. (Suspension 2 Days)
before part photos.
B

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: