



KAN FOOK SING MOTOR WORKSHOP

51 Choa Jua Road Singapore 680157

Tel: (65) 6747 9300, 6830 2126, 6830 4381

Fax: (65) 6748 0000, 6831 8426

E-mail: kfs@pacific.net.sg Website: www.kfs.net.sg

Insurance Reg No: 12-458-TR

Acc Reg No: 12-458-TR

TP INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)
SHUKLA TRANSPORT AND GENERAL SERVICES

Singapore

PARTICULARS OF CLAIM

Claim Type	THIRD PARTY	Ref No:	
Policy No		Date of Loss:	01/10/2021
Vehicle Reg. No.	YP9299R	Driveable?	
Party At Fault	UNKNOWN		
Make/Model	MITSUBISHI FK61FM, 7.5 D (M)	Vehicle Reg. Date:	01/08/2018
Vehicle Colour	WHITE		
Engine No	6M60241645	Chassis No:	FK62FMA40023
Odometer	0 KM		
Paint Type			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Description of Accident/Loss	REFER TO GIA REPORT		
Present Location	KAN FOOK SING MOTOR WORKSHOP (DEFU)		

COST OF CLAIMS

	Amount
Parts	0.00
Miscellaneous Items	1,300.00
Labour	4,800.00
Paintwork Labour	1,500.00
Towing	0.00
Gross Total (S\$)	7,600.00
+ GST 7.00% (S\$)	532.00
Nett Amount (S\$)	8,132.00

This claim is handled by: MT TAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	SIDE PANEL LOGO RH / Base SCR	1,300.00 ?
Sub Total (S\$)			1,300.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAYPAINTING CHARGES	New	1,500.00 ?
<u>Labour Items</u>			
2	TO REMOVE ALL NECESSARY AFFECTED PARTS, TO SUPPLY MATERIALS AND FABRICATE SIDE PANEL RH	New	4,800.00 ?
Gross Labour Cost (S\$)			6,300.00

Kan Fook Sing Motor Workshop/YP9299R/06/10/2021 11:55. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR DETAILS**Reference**

Part Source: (Last Synchronised 06 Oct 2021)
 Parts: N/A MITSUBISHI FK61FM 7.5 D (M) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Kan Fook Sing Motor Workshop/YP9299R/06/10/2021 11:55
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

There are no new parts selected.

Kan Fook Sing Motor Workshop/YP9299R/06/10/2021 11:55 Not valid without Reference section
 Generated using Merimen e-Claims IEAS

LINK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Photo prices are subject to confirmation
- Third party is on a "Without Prejudice" basis
- No illegal motor repairs allowed
- Supplemental repairs must be resurveyed and subject to prior approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Kan Fook Sing

25/10/21

P/P

5 days

before paint photos

After paint photos