



開 福 星 啤 啤 工 廠 **KAN FOOK SING MOTOR WORKSHOP**

81 Choa Lane 15 Singapore 638147
 Tel (65) 6747 9999, 6959 2126, 6959 4351
 Fax (65) 6746 1036, 6281 8428

E-mail: kfs@pacific.net.sg • Website: www.carparts.com.sg

Business Reg No. T2 499-30X
 Job Reg No. M9 100N, 023-1

TP INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)
SHUKLA TRANSPORT AND GENERAL SERVICES

Singapore

PARTICULARS OF CLAIM

Claim Type	THIRD PARTY	Ref. No:	
Policy No.		Date of Loss:	01/10/2021
Vehicle Reg. No.	YP9299R	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	MITSUBISHI FK61FM, 7.5 D (M)	Vehicle Reg. Date:	01/08/2018
Vehicle Colour:	WHITE		
Engine No:	6M60241645	Chassis No:	FK62FMA40023
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Description of Accident/Loss	REFER TO GIA REPORT		
Present Location:	KAN FOOK SING MOTOR WORKSHOP (DEFU)		

COST OF CLAIMS

	Amount
Parts	0.00
Miscellaneous Items	1,300.00
Labour	4,800.00
Paintwork Labour	1,500.00
Towing	0.00
Gross Total (S\$)	7,600.00
+ GST 7.00% (S\$)	532.00
Nett Amount (S\$)	8,132.00

This claim is handled by: MT TAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	SIDE PANEL LOGO RH / Size SCR	1,300.00 ?
Sub Total (\$\$)			1,300.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAYPAINTING CHARGES	New	1,500.00 ?
<u>Labour Items</u>			
2	TO REMOVE ALL NECESSARY AFFECTED PARTS, TO SUPPLY MATERIALS AND FABRICATE SIDE PANEL RH	New	4,800.00 ?
Gross Labour Cost (\$\$)			6,300.00

Kan Fook Sing Motor Workshop/YP9299R/06/10/2021 11:55. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 06 Oct 2021)
Parts: N/A MITSUBISHI FK61FM 7.5 D (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Kan Fook Sing Motor Workshop/YP9299R/06/10/2021 11:55
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

There are no new parts selected.

Kan Fook Sing Motor Workshop/YP9299R/06/10/2021 11:55 Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LUK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary damage must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Guo Qiang

25/10/21

P/P

before paint photos

After paint photos