



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

--

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP/CHINA(YQ2471A)
Policy No:		Date of Loss:	05/10/2021
Vehicle Reg. No.:	SMM798J	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	KOH POH PENG(GAO BAOPING)	Driver (Insured):	KALIYA PERUMAL SHANMUGAM
Make/Model:	TOYOTA VIOS, 1.5 E (A)	Vehicle Reg. Date:	10/10/2007
Vehicle Colour:	SILVER		
Engine No:	1NZX632223	Chassis No:	MR053HY9305030589
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Description of Accident/Loss	REFER TO GIA REPORT ATTACHED.		
Remarks:	VEHICLE CURRENTLY LYING AT YISHUN WORKSHOP.		
Present Location:	CHENG HOE MOTOR PTE LTD (YISHUN)		

COST OF CLAIMS

	Amount
Parts	1,079.00
Miscellaneous Items	200.00
Labour	1,330.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,609.00
+ GST 7.00% (S\$)	182.63
Nett Amount (S\$)	2,791.63

This claim is handled by: SHARON CHIONG BENG CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 08 Oct 2021)**Parts:** 143 TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Cheng Hoe Motor Pte Ltd/SMM798J/11/10/2021 12:27**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC REAR BUMPER	0.00	0.00	*165.00 F
2	1		*1 PC REAR BUMPER LH REFLECTOR	0.00	0.00	*35.00 F
3	1		*1 PC REAR BUMPER LH SIDE RETAINER	0.00	0.00	*35.00 F
4	1		*6 PCS REAR BUMPER CLIPS @1.5/PC	0.00	0.00	*9.00 F
5	1		*1 PC REAR BOOT	0.00	0.00	*320.00 F
6	1		*1 PC REAR BOOT LOGO	0.00	0.00	*30.00 F
7	1		*1 PC REAR BOOT EMBLEM (VIOS)	0.00	0.00	*35.00 F
8	1		*1 PC REAR BOOT OUTER GARNISH	0.00	0.00	*75.00 F
9	1		*1 PC REAR BOOT INNER LOCK	0.00	0.00	*40.00 F
10	1		*1 PC REAR BOOT INNER RUBBER	0.00	0.00	*45.00 F
11	1		*1 PC LH TAILLAMP	0.00	0.00	*95.00 F
12	1		*1 PC REAR CENTRE PANEL	0.00	0.00	*195.00 F

F=Franchise part.

Total Parts (S\$) **1,079.00**

Cheng Hoe Motor Pte Ltd/SMM798J/11/10/2021 12:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	1 SET REVERSE SENSOR	200.00
Sub Total (\$)			200.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	600.00
2	PUTTY & RESPRAY ON REAR BUMPER,BOOT,REAR PANEL,REAR LH FENDER	New	700.00
3	RUSTPROOFING	New	30.00
Gross Labour Cost (\$)			1,330.00

Cheng Hoe Motor Pte Ltd/SMM798J/11/10/2021 12:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >