

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

D

Estimate

Vehicle No:

Make and model:

Chassis :

SGZ 9864 U
 TOYOTA RUSH
 MR2BE3BE700013650

Qty Spare partsList price

2007

1	Tailgate	\$		✓ 945.60	DDV ✓
1	Tailgate "RUSH" emblem	\$	79.80	104.44	NECV ✓
1	Tailgate spare tyre outer cover	\$	865.40	1,539.90	BR ✓
1	Tailgate spare tyre inner cover	\$		355.50	NDX
1	Tailgate spare tyre bracket	\$		286.80	NDX
1	Tailgate lock	\$		145.90	NDX
1	Tailgate inner trim board	\$		✓ 769.80	BR ✓
1	Tailgate weatherstrip	\$		316.60	NDX
1	Tailgate absorber stay	\$		98.80	NDX
1	Rear bumper	\$	780.30	987.60	DDV ✓
1	Rear bumper RH side retainer	\$		✓ 42.70	} NECV ✓
1	Rear bumper LH side retainer	\$		✓ 42.70	
1	Rear bumper RH reflector	\$		50.80	} NDX
1	Rear bumper LH reflector	\$		50.80	
1	Rear bumper towing cover	\$		28.20	NDX
1	Rear bumper RH number plate lamp	\$		✓ 52.50	MIS ✓
1	Rear bumper LH number plate lamp	\$		✓ 52.50	BR ✓
1	RH taillamp assy	\$	365.10	556.90	BR ✓
1	LH taillamp assy	\$	365.10	556.90	BR ✓
1	End panel (outer)	\$	287.40	313.70	DDV ✓
1	End panel (inner)	\$		513.60	NDX
1	End panel inner garnish	\$		83.10	NDX
1	Exhaust silencer	\$		708.50	NDX
1	Rear RH fender inner trim board	\$		458.70	NDX

\$ 4,648.90 9,062.54
 -25% \$ 1,162.23 2,265.64
 \$ 3,486.68 6,796.91

Qty Spare partsSpecial Nett price

1	Tailgate RH artwork sticker	\$	20.00	35.00	NECV ✓
1	Tailgate LH artwork sticker	\$	40.00	65.00	NECV ✓
1	Tailgate windscreen glass sealant	\$	30.00	70.00	NECV ✓
1	Tailgate windscreen glass inner seal	\$		50.00	NDX
1 set	Tailgate inner trim board clips	\$	30.00	60.00	NECV ✓

- 1set Rear bumper clips
- 1set Rear bumper reverse sensor
- 1 Rear bumper RH artwork sticker
- 1 Rear bumper LH artwork sticker

\$ 30.00	70.00	NEC ✓
\$ 200.00	280.00	SE ✓
\$	35.00	} RPTX
\$	35.00	
<u>350.00</u>		

Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts.
To panel beating, cut / weld and re-align all affected panels

\$ 600.00	1,000.00
-----------	----------

Spray painting on affected panels

\$ 500.00	1,000.00
-----------	----------

Check wiring and lighting system

\$	80.00	NNX
----	-------	-----

Apply rust coating chemical on affected panels

\$	60.00	NNX
----	-------	-----

Remove and reinstall tailgate windscreen glass to assist repair

\$ 120.00	200.00
-----------	--------

Remove and replace tailgate inner mechanism to new tailgate

\$ 80.00	200.00
----------	--------

Remove and replace rear bumper reverse sensors

\$ 60.00	100.00
----------	--------

Remove and replace rear inner trims, garnish and boards to assist repair

\$	240.00	NNX
<u>1360.00</u>		

Total: \$ 10,376.91

Survey and Resurvey not necessary.

7/10/2021

1545 hrs

TGum Min

Long sum repair
Repair days 5

Parts	3,486.68
SN	350.00
Labour	1,360.00
	<u>5196.68</u>
@20%	1039.34
	<u>4157.34</u>

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LS 4/150/2

TGum Min

11/10/2021