

AIG

REPAIR PERFORMANCE INVOICE

| | |
|----------------|-------------------|
| Vehicle number | FBR3923Z |
| Make / Model | YAMAHA R15 |
| Chassis number | ME1RG525BK0061101 |
| Accident date | 4/10/21 |
| Reference | KK2110-04 |

Thianan@Lkhauto.com
 82235769
 7/10/21 1300

LIS after repair photo
 wp 4 days
 4

F: 2950

Qty Particulars Unit Price - SGD \$

| Qty | Particulars | Unit Price - SGD \$ |
|---|---|-----------------------------------|
| <u>PARTS REPLACEMENT - LIST ITEMS</u> | | |
| 1 | EXHAUST SILENCER X Find cap | 50 mm 600.00 ✓ SCR |
| 2 | EXHAUST SILENCER COVER | 85 200.00 ✓ SCR |
| 1 | PILLION FOOTREST | 60 90.00 ✓ SCR |
| 1 | DRIVER FOOTREST | 35 90.00 ✓ SCR |
| 1 | DRIVER FOOTREST BRACKET | 120.00 X SVC |
| 1 | BRAKE PEDAL | 55 90.00 ✓ SCR |
| 1 | FRONT HEADLAMP | 135 400.00 ✓ SCR |
| 1 | FRONT HEADLAMP BRACKET | 12.00 ? ✓ SCR |
| 1 | FRONT HEADLAMP FAIRING OUTER | 750 350.00 ✓ Cut |
| 1 | FRONT HEADLAMP FAIRING INNER | 150 350.00 ✓ Cut |
| 2 | FRONT FAIRING SMALL LH/RH | 80 100 240.00 ✓ Cut |
| 1 | WHEEL SHAFT | 250.00 X SVC |
| 2 | AIR INTAKE COVER | 600 280.00 BT - LH |
| 1 SET | BALANCER | 60 150.00 MIS |
| 1 | HANDLEBAR | 35 280.00 ? ✓ BT |
| 1 SET | FRONT FORK | 450 650.00 ? ✓ BT |
| 1 | FRONT FORK BRACKET (UPPER/LOWER) | 180.00 ? ✓ lower bt |
| 1 | FRONT FENDER | 250.00 X SVC |
| 1 | LH FAIRING INNER/OUTER | 100 700.00 ✓ SCR outer |
| 1 | RH FAIRING INNER/OUTER | 100 700.00 ✓ SCR Outer |
| 1 | LH MIDDLE FAIRING | 200.00 X SVC |
| 1 | RH MIDDLE FAIRING | 200.00 X SVC |
| 1 | LH LOWER FAIRING | 80 200.00 ✓ SCR |
| 1 | RH LOWER FAIRING | 80 200.00 ✓ SCR |
| 1 | METER | 300.00 ? X nn |
| 1 | BRAKE PUMP | 500.00 ? X R |
| 1 | FUEL TANK (CENTRE) | 350.00 X r |
| 1 | FUEL TANK FAIRING (SIDE) | 280.00 ✓ DIS |
| | | 8212.00 |
| | Less 10 % | 821.20 |
| | Subtotal | 7390.80 |
| | Balance C/F | 7390.80 |
| <u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u> | | |
| 1 | WINDSHIELD (AFTER MARKET) | 150 300.00 ✓ DIS |
| 1 | WINDMIRROR (AFTER MARKET) | LH SVC 150 280.00 ✓ PLSCF |
| 1 | BRAKE LEVER (AFTER MARKET) | 30 150.00 ✓ SCR |
| 1 | CLUTCH LEVER (AFTER MARKET) | 30 150.00 ✓ SCR |
| 1 SET | SIGNAL LAMP (AFTER MARKET) | 100 180.00 ✓ CR/hi/s |
| 1 | FRONT SPORT RIM | 20.00 ? X NN |
| 1 | FORK OIL | 20.00 ? X NN |
| 1 | FORK SEAL | nn 80.00 X ATG |
| | Subtotal | 1480.00 |
| | Balance C/F | 8870.80 |
| <u>LABOUR AND MISCELLANEOUS CHARGES</u> | | |
| 1 | TO CHECK WIRING SYSTEM | 60.00 20 |
| 2 | TO REMOVE AND REPLACE EXHAUST SILENCER | 200.00 30 |
| 3 | TO R&R SUSPENSION, HANDLE BAR, HEADLAMP & FAIRING | 200 600.00 150 |
| 4 | TO SPRAY FENDER, FAIRINGS AND AFFECTED AREAS | 100 1000.00 X NN |
| | Subtotal | 1860.00 |
| | Grand total | 11076.00 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey
- To dis
- Part
- Time
- Not
- is subject to

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To survey damaged part(s) during resurvey
- Prices are subject to confirmation
- Party survey is on a "Without Prejudice" basis
- Final modification(s) is allowed
- Secondary item(s) must be resurveyed and is subject to final approval from Insurance Company

KARZ WORKS PTE LTD
 53 UBI AVENUE 1 #01-23, PAYA UBI INDUSTRIAL PARK
 SINGAPORE 408934
 (TEL) 6 8 4 4 5 9 3 4 (FAX) 6 8 4 4 2 4 7 4 (E-MAIL) KARZWORKSSG@GMAIL.COM

AIG

REPAIR PERFORMA INVOICE

| | |
|----------------|-------------------|
| Vehicle number | FBR3923Z ✓ |
| Make / Model | YAMAHA R15 |
| Chassis number | ME1RG525BK0061101 |
| Accident date | 4/10/21 |
| Reference | KK2110-04 |

| Qty | Particulars | Unit Price - SGD |
|-----|---|-------------------|
| | <u>PARTS REPLACEMENT - LIST ITEMS</u> | |
| 1 | RADIATOR | 250 600.00 ✓ SCR |
| | | 600.00 |
| | Less 10 % | 60.00 |
| | Subtotal | 540.00 |
| | Balance C/F | 540.00 |
| | <u>LABOUR AND MISCELLANEOUS CHARGES</u> | |
| 1 | TO CHECK WIRING SYSTEM | 200.00 ✓ repeated |
| | Subtotal | 200.00 |
| | Grand total | 740.00 |