

AIG

REPAIR PERFORMA INVOICE

Vehicle number	FBR3923Z
Make / Model	YAMAHA R15
Chassis number	ME1RG525BK0061101
Accident date	4/10/21
Reference	KK2110-04

Thovan@Lkhauto.com
 82235769

7/10/21 1300

L/S after repair photo
 wp 3 days
 4

Qty	Particulars	Unit Price - SGD \$
PARTS REPLACEMENT - LIST ITEMS		
1	EXHAUST SILENCER X Fnd cap	50 600.00 ✓ SCR
2	EXHAUST SILENCER COVER	85 200.00 ✓ SCR
1	PILLION FOOTREST	60 90.00 ✓ SCR
1	DRIVER FOOTREST	35 90.00 ✓ SCR
1	DRIVER FOOTREST BRACKET	120.00 X SVC
1	BRAKE PEDAL	55 90.00 ✓ SCR
1	FRONT HEADLAMP	185 400.00 ✓ CRG
1	FRONT HEADLAMP BRACKET	12.00 7. ✓ SCR
1	FRONT HEADLAMP FAIRING OUTER	250 350.00 ✓ CUT
1	FRONT HEADLAMP FAIRING INNER	150 350.00 ✓ CUT
2	FRONT FAIRING SMALL LH/RH	80 240.00 ✓ CUT
1	WHEEL SHAFT	250.00 X SVC
2	AIR INTAKE COVER	60 280.00 BT - LH
1 SET	BALANCER	60 150.00 mis ✓
1	HANDLEBAR	95 280.00 7. ✓ BT
1 SET	FRONT FORK	450 650.00 7. ✓ BT
1	FRONT FORK BRACKET (UPPER/LOWER)	180.00 7. ✓ LOWER
1	FRONT FENDER	250.00 X SVC
1	LH FAIRING INNER/OUTER	200 700.00 ✓ SCR outer
1	RH FAIRING INNER/OUTER	200 700.00 ✓ SCR outer
1	LH MIDDLE FAIRING	200.00 X SVC
1	RH MIDDLE FAIRING	200.00 X SVC
1	LH LOWER FAIRING	80 200.00 ✓ SCR
1	RH LOWER FAIRING	80 200.00 ✓ SCR
1	METER	300.00 7. X
1	BRAKE PUMP	500.00 7. X
1	FUEL TANK (CENTRE)	350.00 X r
1	FUEL TANK FAIRING (SIDE)	280.00 ✓ DIS
		8212.00
	Less 10 %	821.20
	Subtotal	7390.80
	Balance C/F	7390.80
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
1	WINDSHIELD (AFTER MARKET)	150 300.00 ✓ DIS
1	WINDMIRROR (AFTER MARKET)	150 280.00 ✓ RH
1	BRAKE LEVER (AFTER MARKET)	30 150.00 ✓ SCR
1	CLUTCH LEVER (AFTER MARKET)	30 150.00 ✓ SCR
1 SET	SIGNAL LAMP (AFTER MARKET)	100 180.00 ✓ CRG/mis
1	FRONT SPORT RIM	300 ✓ BT 180.00 X SVC
1	FORK OIL	20.00 7. X NN
1	FORK SEAL	20.00 7. X NN
1	REAR NUMBER PLATE	80.00 X NC
	Subtotal	1480.00
	Balance C/F	8870.80
LABOUR AND MISCELLANEOUS CHARGES		
1	TO CHECK WIRING SYSTEM	60.00 20
2	TO REMOVE AND REPLACE EXHAUST SILENCER	200.00 30
3	TO R&R SUSPENSION, HANDLE BAR, HEADLAMP & FAIRING	200 600.00 150
4	TO SPRAY FENDER, FAIRINGS AND AFFECTED AREAS	100 1000.00 X NN
	Subtotal	1860.00
	Grand total	11076.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey
- To disassemble
- Part(s) are still
- Time taken
- No further
- is subject to

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To replace damaged part(s) during resurvey
- Part(s) are subject to confirmation
- Part(s) survey is on a "Without Prejudice" basis
- No further
- Final modification(s) is allowed
- Final modification(s) must be resurveyed and subject to final approval from Insurance Company

KARZ WORKS PTE LTD
 53 UBI AVENUE 1 #01-23, PAYA UBI INDUSTRIAL PARK
 SINGAPORE 408934
 (TEL) 6 8 4 4 5 9 3 4 (FAX) 6 8 4 4 2 4 7 4 - (E-MAIL) KARZWORKSSG@GMAIL.COM

AIG

REPAIR PERFORMA INVOICE

Vehicle number	FBR3923Z ✓
Make / Model	YAMAHA R15
Chassis number	ME1RG525BK0061101
Accident date	4/10/21
Reference	KK2110-04

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	RADIATOR	250 600.00 ✓ SCV
		600.00
	Less 10 %	60.00
	Subtotal	540.00
	Balance C/F	540.00
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
1	TO CHECK WIRING SYSTEM	200.00 X no repeated
	Subtotal	200.00
	Grand total	740.00