



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2203437
3 ANSON ROAD #16-00	INV Date	06/06/2022
SPRINGLEAF TOWER	Reference	CC6/CTI21010337/Uea3q2
SINGAPORE 079909	Code	CTI

PROFESSIONAL SERVICE FEE

Vehicle No.	SJY 7576J
Insured Veh.	YP 4589L
Claim No.	SNM21D205731/C02
Policy No.	DMCVSNW00121522102
Accident Date	07/10/2021
Inspection Date	07/10/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Ref: CC6/CTI21010337/Uea3q2

Date: 06/06/2022

Code: CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 4589L	Veh. Inspected	SJY 7576J
Policy No.	DMCVSNW00121522102	Coverage (\$)	0.00
Claim No.	SNM21D205731/C02	Excess (\$)	0.00
Assign From		Assign Date	07/10/2021

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ E250 CGI (A)	c.c	1796
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	WDD2120472A146365	Colour	SILVER
Odometer	63669 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R16	HABILEAD	6 mm
L/H Front Tyre	225/55 R16	HABILEAD	6 mm
R/H Rear Tyre	225/55 R16	HABILEAD	6 mm
L/H Rear Tyre	225/55 R16	HABILEAD	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/10/2021	Inspection Date	07/10/2021
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
--	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJY 7576J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DISTORTED	2,231.32	1,789.31
1	FRONT BUMPER SIDE RETAINER O/S	CRACKED	145.50	105.35
1	FRONT BUMPER PDC SENSOR O/S	SHORTED	199.00	182.00
1	FRONT BUMPER REINFORCEMENT	TWISTED	788.21	581.69
1	FRONT BUMPER FOG LAMP GARNISH O/S	DAMAGED	198.80	166.50
1	FRONT BUMPER FOG LAMP O/S	CRACKED	485.90	254.80
1	FRONT BUMPER SPONGE	TORN	221.00	168.00
1	SET FRONT BUMPER CLIPS & RIVET	NECESSARY	60.00	60.00
1	FRONT GRILLE	CRACKED	1,055.00	1,045.20
1	HEADLAMP O/S	BROKEN	3,200.00	1,566.25
1	FRONT FENDER O/S	TO REPAIR SEE LABOUR	1,415.00	-
1	FRONT FENDER INNER SHIELD O/S	NOT NECESSARY	322.80	-
1	SET FRONT FENDER INNER SHIELD CLIPS O/S	NOT NECESSARY	50.00	-
1	FRONT FENDER EMBLEM O/S	NECESSARY	120.00	105.00
1	BONNET	TO REPAIR SEE LABOUR	2,550.00	-
1	FRONT SPORT RIM O/S (CUT)	NOT CONSISTENT WITH THE IMPACT	900.00	-
	LESS 10% DISCOUNT		-	-602.41
			13,942.53	5,421.69
<u>LABOUR</u>				
	TO CHECK WIRING .		50.00	20.00
	TO DISMANTLE & REPLACED FRT PDC SENSOR .		80.00	50.00
	TO SPRAY RUST PROOFING .	NOT NECESSARY	50.00	-
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	TO RESET & REPROGRAMME DIAGNOSIS SYSTEM.		180.00	50.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF FRONT FENDER O/S AND BONNET .		800.00	550.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY & SPRAY PAINTING.		1,080.00	680.00
			2,360.00	1,350.00
	GRAND TOTAL		16,302.53	6,771.69
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,400.00

Report Ref No. CC6/CTI21010337/Uea3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJY 7576J

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R









LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJY 7576J

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJY 7576J

RE-INSPECTION

