

LKK Asher

Not Allowed

LKK

7/10/21

1/58 5400 / 4 days

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

VEHICLE No: SJY 7576J

1PC	FRONT BUMPER	D/S	1789.31	\$2,231.32
1PC	FRONT BUMPER SIDE RETAINER O/S	one	105.35	\$145.50
1PC	FRONT BUMPER PDC SENSOR O/S	should	182.00	\$199.00
1PC	FRONT BUMPER REINFORCEMENT	YWI	581.69	\$788.21
1PC	FRONT BUMPER FOG LAMP GARNISH O/S	dayeb	166.50	\$198.80
1PC	FRONT BUMPER FOG LAMP O/S	one	254.80	\$485.90
1PC	FRONT BUMPER SPONGE	YWI	168.00	\$221.00
1SET	FRONT BUMPER CLIPS & RIVET	all		\$60.00
1PC	FRONT GRILLE	one	1045.20	\$1,055.00
1PC	HEADLAMP O/S	BW	1566.25	\$3,200.00
1PC	FRONT FENDER O/S	R		\$1,415.00 X
1PC	FRONT FENDER INNER SHIELD O/S	11		\$322.80 X
1SET	FRONT FENDER INNER SHIELD CLIPS O/S	11		\$50.00 X
1PC	FRONT FENDER EMBLEM O/S	all	105.00	\$120.00
1PC	BONNET	R		\$2,550.00 X
1PC	FRONT SPORT RIM O/S	cut all		\$900.00 X
			(102)	\$13,942.53

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REPLACED FRT PDC SENSOR	\$80.00	50
TO SPRAY RUST PROOFING	\$50.00	X
TO CONDUCT WHEEL ALIGNMENT	\$120.00	X
TO RESET & REPROGRAMME DIAGNOSIS SYSTEM	\$180.00	50
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$800.00	550
TO PUTTY & SPRAY PAINTING	\$1,080.00	680
TOTAL	\$16,302.53	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2-6024-1
102
P-5421.69
L-1350
6771.69
202
5417