

Estimation

Date
Vehicle SLZ 6206 E
Make/Model TOYOTA C-HR
Chassis No. ZYX102068653

No.	Description	Unit	Unit Price	Amount
	Parts Replacment			
1	FRONT DOOR LH <i>Repair</i>	1	\$	-
2	FRONT DOOR WINDOW MOULDING LH <i>see X</i>	1	\$	-
3	FRONT DOOR INNER WINDOW MOULDING LH <i>X</i>	1	\$	-
4	FRONT DOOR OUTER GARNISH LH <i>see /</i>	1	\$	-
5	FRONT DOOR LOCK LH <i>X</i>	1	\$	-
6	FRONT DOOR LOCK CATCH LH <i>X</i>	1	\$	-
7	FRONT DOOR WEATHERSTRIP LH <i>X</i>	1	\$	-
8	FRONT DOOR INNER WEATHERSTRIP LH <i>X</i>	1	\$	-
9	REAR DOOR LH <i>Repair bt /</i>	1	\$	-
10	REAR DOOR WINDOW MOULDING LH <i>X</i>	1	\$	-
11	REAR DOOR INNER WINDOW MOULDING LH <i>X</i>	1	\$	-
12	REAR DOOR OUTER GARNISH LH <i>mis /</i>	1	\$	-
13	REAR DOOR LOCK LH <i>X</i>	1	\$	-
14	REAR DOOR LOCK CATCH LH <i>X</i>	1	\$	-
15	REAR DOOR INNER BOARD LH <i>X</i>	1	\$	-
16	REAR DOOR POWER WINDOW MOTOR LH <i>X</i>	1	\$	-
17	REAR DOOR WINDOW REGULATOR LH <i>X</i>	1	\$	-
18	REAR DOOR HINGE LH <i>X</i>	2	\$	-
19	REAR DOOR WEATHERSTRIP LH <i>Repair</i>	1	\$	-
20	REAR DOOR INNER WEATHERSTRIP LH <i>X</i>	1	\$	-
21	ROCKER PANEL LH <i>see bt /</i>	1	\$	-
22	SIDE SKIRT LH <i>see /</i>	1	\$	-
23	REAR WINDSCREEN MOULDING <i>X</i>	1	\$	-
24	REAR FENDER LH <i>Repair X</i>	1	\$	-
25	REAR FENDER COWLING LH <i>X</i>	1	\$	-
26	REAR WHEEL ARC PROTECTOR LH <i>see /</i>	1	\$	-
27	TAIL LAMP LH <i>X</i>	1	\$	-
28	REAR BUMPER <i>X</i>	1	\$	-
29	REAR BUMPER LOWER <i>X</i>	1	\$	-
30	REAR BUMPER RETAINER LH <i>X</i>	1	\$	-
31	REAR ABSORBER LH <i>X</i>	1	\$	-
32	REAR KNUCKLE BEARING LH <i>X</i>	1	\$	-
33	REAR BEARING HUB LH <i>X</i>	1	\$	-
34	REAR AXLE <i>X</i>	1	\$	-
35	REAR RIM LH <i>see /</i>	1	\$	-
			Total	\$ -
			Less 25%	\$ -

			Total	\$	-
--	--	--	--------------	-----------	---

S/Nett Items					
1	FRONT DOOR INNER BOARD CLIPS	100 X	1	100	\$ 100.00
2	FRONT DOOR OUTER GARNISH CLIPS	100 X	1	100	\$ 30 100.00
3	FRONT DOOR VISOR LH	X	1	300	\$ 300.00
4	REAR DOOR INNER BOARD CLIPS	100 X	1	100	\$ 40 100.00
5	REAR DOOR OUTER GARNISH CLIPS	X	1	100	\$ 100.00
6	REAR DOOR VISOR LH	X	1	300	\$ 300.00
7	SIDE SKIRT CLIPS	100 X	1	100	\$ 30 100.00
8	REAR WINDSCREEN SEALANT	X	1	150	\$ 150.00
9	REAR FENDER COWLING CLIPS	X	1	100	\$ 100.00
10	REAR WHEEL ARC PROTECTOR CLIPS	100 X	1	100	\$ 30 100.00
11	TAIL LAMP CLIPS	X	1	50	\$ 50.00
12	REAR BUMPER CLIPS	X	1	100	\$ 100.00
13	REAR TYRE LH	X	1	800	\$ 800.00
			Total	\$	2,400.00

LABOUR					
1	PANEL BEATING ON AFFECTED AREAS		1	1600	\$ 500 1,600.00
2	SPRAY PAINT ON AFFECTED AREAS		1	1200	\$ 650 1,200.00
3	TO RNR REAR WINDSCREEN		1	400	\$ X 400.00
4	TO CHECK WIRING AND TAIL LAMP FUNCTION		1	150	\$ X 150.00
5	TO RNR REAR INNER TRIM AND UPHOISTERY		1	400	\$ 60 400.00
6	TO CHECK WHEEL ALIGNMENT AND ADJUST		1	250	\$ 60 250.00
7	TO RNR UNDERCARRIAGE		1	250	\$ X 250.00
8	TO CHECK WHEEL BALANCING		1	250	\$ X 250.00
9	TO CHECK WATER LEAK		1	150	\$ X 150.00
10	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS		1	600	\$ X 600.00
11	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION		1	150	\$ X 150.00
12	TO PERFORM RUST PROOFING		1	400	\$ X 400.00
13	TO RNR REAR AND FRONT DOOR MECHANISM		1	600	\$ 100 600.00

Total Labour	\$	6,400.00
Parts Replacement Amount	\$	2,400.00
Total Amount	\$	8,800.00

Rasul
 Hp 900110068
 5 days
 4/8
 07/10/21 @ 1545
 Resurvey after repair
 Request wheel alignment copy
 email: rasul@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

 Acknowledged by Repairer
 Signature:
 Date:

Truck / Trailer
 Lorry / Taxi / Van / Bus