



AP Automotive Services

AP AUTOMOTIVE SERVICES PTE LTD
 ROC: 202022890H
 BLOCK 9006
 TAMPINES STREET 93 #01-202
 SINGAPORE 528840
 TEL: 6784 4465
 FAX: 6787 4886

Estimation

Date _____
 Vehicle SLZ 6206 E
 Make/Model TOYOTA C-HR
 Chassis No. ZYX102068653

No.	Description	Unit	Unit Price	Amount
	Parts Replacment			
1	FRONT DOOR LH Repair X	1	\$ Repair	- X
2	FRONT DOOR WINDOW MOULDING LH sc X n	1	\$ 145.00	- X
3	FRONT DOOR INNER WINDOW MOULDING LH X n	1	\$ 156.00	- X
4	FRONT DOOR OUTER GARNISH LH sc	1	\$ 404.00	- 380 X
5	FRONT DOOR LOCK LH X n	1	\$ 325.00	- X
6	FRONT DOOR LOCK CATCH LH X n	1	\$ 80.00	- X
7	FRONT DOOR WEATHERSTRIP LH X n	1	\$ 297.00	- X
8	FRONT DOOR INNER WEATHERSTRIP LH X n	1	\$ 311.00	- X
9	REAR DOOR LH Repair bt	1	\$ 1371.00	- 1255 X
10	REAR DOOR WINDOW MOULDING LH X n	1	\$ 123.00	- X
11	REAR DOOR INNER WINDOW MOULDING LH X n	1	\$ 98.00	- X
12	REAR DOOR OUTER GARNISH LH Mis	1	\$ 456.00	- 332 X
13	REAR DOOR LOCK LH X n	1	\$ 317.00	- X
14	REAR DOOR LOCK CATCH LH X n	1	\$ 80.00	- X
15	REAR DOOR INNER BOARD LH X n	1	\$ 543.00	- X
16	REAR DOOR POWER WINDOW MOTOR LH X n	1	\$ 409.00	- X
17	REAR DOOR WINDOW REGULATOR LH X n	1	\$ 278.00	- X
18	REAR DOOR HINGE LH X n	2 @ 62	\$ 124.00	- X
19	REAR DOOR WEATHERSTRIP LH Repair	1	\$ 295.00	- 175 X
20	REAR DOOR INNER WEATHERSTRIP LH X n	1	\$ 306.00	- X
21	ROCKER PANEL LH sc bt	1	\$ 97.00	- 546 X
22	SIDE SKIRT LH sc	1	\$ 994.00	- 541 X
23	REAR WINDSCREEN MOULDING X n	1	\$ -	- X
24	REAR FENDER LH Repair X n	1	\$ -	- X
25	REAR FENDER COWLING LH X n	1	\$ 170.00	- X
26	REAR WHEEL ARC PROTECTOR LH sc	1	\$ 379.00	- 237 X
27	TAIL LAMP LH X n	1	\$ 478.00	- X
28	REAR BUMPER X n	1	\$ 621.00	- X
29	REAR BUMPER LOWER X n	1	\$ 435.00	- X
30	REAR BUMPER RETAINER LH X n	1	\$ 123.00	- X
31	REAR ABSORBER LH X n	1	\$ 377.00	- X
32	REAR KNUCKLE BEARING LH X n	1	\$ 298.00	- X
33	REAR BEARING HUB LH X n	1	\$ 315.00	- X
34	REAR AXLE X n	1	\$ 1972.00	- X
35	REAR RIM LH X sc	1	\$ 789.00	- 300 S/M X
			Total	\$ 13,986.00
			Less 25%	\$ -

3466
 259
 2599.50
 S/M - 300

			Total	\$	10489.50	-
--	--	--	--------------	----	----------	---

S/Nett Items						
1	FRONT DOOR INNER BOARD CLIPS	100 X n	1	100	\$	100.00
2	FRONT DOOR OUTER GARNISH CLIPS	100 n	1	100	\$	30 100.00
3	FRONT DOOR VISOR LH	X n	1	300	\$	300.00
4	REAR DOOR INNER BOARD CLIPS	100 n	1	100	\$	40 100.00
5	REAR DOOR OUTER GARNISH CLIPS	X n	1	100	\$	100.00
6	REAR DOOR VISOR LH	X n	1	300	\$	300.00
7	SIDE SKIRT CLIPS	n	1	100	\$	30 100.00
8	REAR WINDSCREEN SEALANT	X n	1	150	\$	150.00
9	REAR FENDER COWLING CLIPS	X n	1	100	\$	100.00
10	REAR WHEEL ARC PROTECTOR CLIPS	n	1	100	\$	30 100.00
11	TAIL LAMP CLIPS	X n	1	50	\$	50.00
12	REAR BUMPER CLIPS	X n	1	100	\$	100.00
13	REAR TYRE LH	X n	1	800	\$	800.00
	Total				\$	2,400.00

LABOUR						
1	PANEL BEATING ON AFFECTED AREAS		1	1600	\$	500 1,600.00
2	SPRAY PAINT ON AFFECTED AREAS		1	1200	\$	650 1,200.00
3	TO RNR REAR WINDSCREEN		1	400	\$	n X 400.00
4	TO CHECK WIRING AND TAIL LAMP FUNCTION		1	150	\$	n X 150.00
5	TO RNR REAR INNER TRIM AND UPHOISTERY		1	400	\$	60 400.00
6	TO CHECK WHEEL ALIGNMENT AND ADJUST		1	250	\$	60 250.00
7	TO RNR UNDERCARRIAGE		1	250	\$	n X 250.00
8	TO CHECK WHEEL BALANCING		1	250	\$	n X 250.00
9	TO CHECK WATER LEAK		1	150	\$	n X 150.00
10	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS		1	600	\$	n X 600.00
11	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION		1	150	\$	n X 150.00
12	TO PERFORM RUST PROOFING		1	400	\$	n X 400.00
13	TO RNR REAR AND FRONT DOOR MECHANISM		1	600	\$	100 600.00
	Total Labour				\$	6,400.00
	Parts Replacement Amount				\$	2,400.00
	Total Amount				\$	8,800.00

2599.50
 300.00
 130.00
 1370.00

 4399.50
 20%
 3519.60

 4535.00

Rasul
 Hp 90010068
 5 days
 4s
 07/10/21 @ 1545
 Resurvey after repair
 Request wheel alignment copy
 email: rasul@lkkauto.com

Total Labour	\$	6,400.00
Parts Replacement Amount	\$	2,400.00
Total Amount	\$	8,800.00

19,289.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

 Acknowledged by Repairer
 Signature:
 Date: