



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:ONG KIAN THENG

Ref: CC4/ASM21010340/Apa3q2
Date: 18/03/2022
Code: ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJQ 9769Z	Veh. Inspected	SKB 3319X
Policy No.	P1235558	Coverage (\$)	0.00
Claim No.	S1M03JC3	Excess (\$)	0.00
Assign From		Assign Date	07/10/2021

2. Vehicle Particulars & Condition

Make & Model	B.M.W. X5	c.c	2979
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WBAZV42060L491781	Colour	BLACK
Odometer	109145 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	255/55 R18	CONTINENTAL	6 mm
L/H Front Tyre	255/55 R18	CONTINENTAL	6 mm
R/H Rear Tyre	255/55 R18	CONTINENTAL	6 mm
L/H Rear Tyre	255/55 R18	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/10/2021	Inspection Date	07/10/2021
Survey held at	NEW ZEN WERKZ PTE LTD 3 KAKI BUKIT ROAD 1, #03-04, SINGAPORE 415935		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**