

NEW ZEN WERKZ PTE LTD

BLK 3 KAKI BUKIT RD 1 #03-04 EUNOS TECHNOLINK SINGAPORE 415935

Blk 3 Kaki Bukit Road 1
03 - 04 Eunos Technolink
Singapore 415935

TP AXA

08th OCT 2021

Xiao Tong

WBAZV42060C491781

Accident date: 04th OCT 2021

Estimated repair cost for vehicle no: SKB3319X BMW X5

S/n	Qty	Items/Nett	U/price	Amount
1	1	front bumper-top		\$1,250.20
2	2	Front Bumper -Lower		\$1,282.30
3	1	Front number plate		\$50.00
4	1	front number plate		\$68.20
5	1	Rear Bumper Side Bracket	\$125.30	\$125.30

Subtotal :- \$2,776.00

658.20

592.38

Labour charges

To Check Wiring System

\$60.00 30

Panel beating

480

\$400.00 200

Spray painting

\$500.00 250

Subtotal :- \$960.00

Total:- \$3,736.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 1072.38

4/5 : 850

02 Days.