

## Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax: 64747770

280, Kampong Ayang Road  
East Coast Centre  
Singapore 436180  
Fax: 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax: 64796601 (AfterSales)  
64796624 (Motorrad)

Steve (LKK)  
26/10/21, 11:00am

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

My Bel sy, 3 days

Estimate No. : b1 59714  
Date Estimated : 06/10/2021  
Prepared By : Foong Shiuh Jye

Page No. : 1 of 5

## - ESTIMATE REPAIR FOR -

Ong Chew Hoon  
99 Yishun Avenue 1  
#09-37

Singapore 769139

## - ACCOUNT - 219

India Int'L Insurance Pte Ltd  
64 Cecil Street  
#04-05 IOB Building  
Singapore 049711

| REGN. NO. | CHASSIS NO.       | REGN. DATE | MODEL      | MILEAGE |
|-----------|-------------------|------------|------------|---------|
| SMT9157M  | WBA5F32020FH99036 | 23/07/2020 | 320i Sedan | 23822   |

## DESCRIPTION

## VALUE

To replace rear bumper including to knock out dented area caused by the accident

857 1,275.00

To respray rear bumper

986 1,038.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

168 177.00

To check electrical wiring system and lighting at the rear section for proper function.

168 177.00

Sundries.

80.00

Total Labour 1: 2,747.00

## DESCRIPTION

## QTY

## PRIC

## VALUE

# TAILPIPE TRIM CHROME D=90MM X

1 125.85 125.85

Mount, lateral X

1 199.95 199.95

REAR BUMPER CARRIER ?

1 493.80 493.80

# TRIM STRIP (SPORT) - Cuf CRH

1 104.20 104.20

# REAR RH TRIM PANEL - Cuf CRH

1 75.25 75.25

REAR BUMPER LH SIDE GUIDE ?

1 134.30 134.30

REAR BUMPER RH SIDE GUIDE ?

1 134.30 134.30

# REAR BUMPER PANEL PRIMED (SP) - 00

1 1,281.30 1,281.30

REAR BUMPER TOWING EYE COVER PRIMED - CR4

1 48.10 48.10

REAR RH REAR REFLECTOR ?

1 39.05 39.05

Total Parts : 2,636.10

**Performance Motors Limited**

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

**E S T I M A T E**

Estimate No. : b1 59714  
Date Estimated : 06/10/2021  
Prepared By : Foong Shiuh Jye

Page No. : 2 of 5

| REGN. NO. | CHASSIS NO.       | REGN. DATE | MODEL      | MILEAGE |
|-----------|-------------------|------------|------------|---------|
| SMT9157M  | WBA5F32020FH99036 | 23/07/2020 | 320i Sedan | 23822   |

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



|                |   |                 |
|----------------|---|-----------------|
| Labour 1       | : | 2,747.00        |
| Parts          | : | 2,636.10        |
| Labour 2       | : | 0.00            |
| Excess         | : | 0.00            |
| Total GST @ 7% | : | 376.82          |
| Grand Total    | : | <u>5,759.92</u> |

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*