

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 18 Nov 2021)**Parts:** N/A TOYOTA HIACE 3.0 (A) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Goldbell Engineering Pte Ltd/GBG438K/18/11/2021 13:24**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*CTR INST PANEL COVER cra ✓	0.00	0.00	*580.00 F
2	1		*AIR CONDITIONING bt ✓	0.00	0.00	*610.00 F
3	1		*EVAPORATOR bt ✓	0.00	0.00	*300.00 F
4	1		*SUPPORT SUB ASSY bt ✓	0.00	0.00	*380.00 F
5	1		*HEAT EXCHANGER bt ✓	0.00	0.00	*1,620.00 F
6	1		*AIR FILTER ASSY cra ✓	0.00	0.00	*680.00 F
7	1		*AIR FILTER ELEMENT cut ✓	0.00	0.00	*250.00 F
8	1		*LOWER AIR FILTER COVER cra ✓	0.00	0.00	*100.00 F
9	1		*SUSPENS INTAKE HOSE cra ✓	0.00	0.00	*125.00 F
10	1		*BRAKE POWER CONTROL bt ✓	0.00	0.00	*600.00 F

F=Franchise part.

Total Parts (S\$)**5,245.00**

Goldbell Engineering Pte Ltd/GBG438K/18/11/2021 13:24. Not valid without Reference section.
Generated using Merimen e-Claims IEAS