

SLV7794M OD CHINA TAI PING

Denise Tay (LKKAuto) <denisetay@lkkauto.com>

Tue 12/10/2021 12:37 PM

To: AutoInsure (Claims) <claims01@autoinsure.com.sg>

Cc: SUR <sur@lkkauto.com>

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLV7794M** (Excess \$0/-). **LUMP SUM REPAIR**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

***NOTED COST PLUS 10% NOT APPLICABLE FOR AUTHORISE WORKSHOP.**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)