



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC19001733/R1tf3e2-1 Date: 26/10/2021 Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLV 6334P	Veh. Inspected	SKA 5370M	
Policy No.	Z18VP05017952	Coverage (\$)	0.00	
Claim No.	18/19/19/VP05/021365	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	07/10/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	NISSAN TEANA 2.5 CVT	c.c	2496	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	JN1BBUJ32Z0002090	Colour	GREY	
Odometer	136974 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	FALKEN	6 mm	
L/H Front Tyre	215/55 R17	FALKEN	6 mm	
R/H Rear Tyre	215/55 R17	FALKEN	6 mm	
L/H Rear Tyre	215/55 R17	FALKEN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	23/01/2019	Inspection Date	28/01/2019	
Survey held at	JINGKIA CAR SERVICES BLK 10,ANG MO KIO INDUSTRIAL PARK 2A #05-09 ANG MO KIO AUTOPOINT . SINGAPORE 568047			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			14 Working Days	