



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462. Tel no. 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
United Overseas Insurance Ltd 146 Robinson Road #02-01 UOI Building Singapore cc	S1000019 / ICUOI1	M/S Eksklusiv Landscape Pte Ltd 1 Bukit Batok Crescent #03-19 Singapore 658064
	Document No. 0	
	Document Date 06/10/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	XZU710R	WKMMV3	21/07/2021	YQ4213R	0	10211	65OD/YQ4213R
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JHHUCV3F80K039474	N04CWN14777	60	Francis Cher T S	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.: DHOM120061422100 ACC DATE:01.10.21 TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				50 100.00
2	L	BP-LPO SUPPLY REGN PLATE (PO#)				80.00
3	B	BP-LAB2 REPLACE AND REFOCUS HEADLAMP.				220.00
4	S	BP-SUBLET RESET AND REPROGRAMM E CU.				220.00
5	S	BP-SUBLET REMOVE AND REINSTALL FRT DASH BOARD (photo) 880 x 2				1760.00
6	S	BP-SUBLET REMOVE AND REGAS AIR CON COMPONENTS TO ASSIST REPAIR.				880.00
7	S	BP-SUBLET REPLACE FRT WIRING HARDNESS ASSY.				880.00
8	S	BP-SUBLET CONDUCT WATER TEST.				220.00
9	S	BP-SUBLET REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, FRT PANEL ASSY, 880 x 3 FRT BUMPER AND INNER PANEL AND AFFECTED PORTION OF CAR.				2640 4400.00

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy

Indicape

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no : 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
United Overseas Insurance Ltd 146 Robinson Road #02-01 UOI Building Singapore cc	S1000019 / ICUOI1 Document No. 0 Document Date 06/10/2021	M/S Eksklusiv Landscape Pte Ltd 1 Bukit Batok Crescent #03-19 Singapore 658064

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	XZU710R	WKMMV3	21/07/2021	YQ4213R	0	10211	65OD/YQ4213R
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JHHUCV3F80K039474	N04CWN14777	60	Francis Cher T S	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	S	BP-SUBLET SPRAY PAINT ON FRT AFFECTED PORTION OF CAR. 3 x 660				1980 2640.00
11	1	H52111-37400 A0 BAR, FR BUMPER / A BR	1.00	967.20		967.20
12	2	H52141-37222 STAY, FR BUMPER, RH / BR	1.00	306.00		306.00
13	3	H52142-37202 STAY, FR BUMPER, LH / BR	1.00	306.00		306.00
14	4	H52021-37022 REINFORCEMENT SUB-AS / BR x nn	1.00	1116.20		1116.20
15	5	H52131-37111 REINFORCEMENT, FR BU / BR	1.00	62.00		62.00
16	6	H52136-37011 REINFORCEMENT, FR BU / BR	1.00	50.80		50.80
17	7	H81110-37751 HEADLAMP ASSY, RH / X nn	1.00	1086.50		1086.50
18	8	H81150-37751 HEADLAMP ASSY, LH / BR	1.00	1086.50		1086.50
19	9	H55701-37070 FRT COWL CAB PANEL / BR	1.00	641.40		641.40
20	0	H53111-37B30 A0 GRILLE, RADIATOR / BR	1.00	701.30		701.30
21	1	H53142-37020 GARNISH, RADIATOR GRILLE, NO.2 / BR	1.00	256.50		256.50
22	2	H53143-37020 GARNISH, RADIATOR GRILLE, NO.3 / BR	1.00	44.20		44.20
23	3	H75315-37100 ORNAMENT, RADIATOR G / BR	1.00	76.50		76.50
24	4	H75311-37330 PLATE, FR NAME, NO.1 / BR	1.00	35.30		35.30
25	5	H75311-37320 PLATE, FR NAME, NO.1 / BR	1.00	37.80		37.80
26	6	H82114-37320 WIRE, ENGINE ROOM, NO.4 / BR	1.00	123.70		123.70
27	7	H52112-37130 EXTENSION, FR BUMPER / BR	1.00	43.70		43.70
28	8	H52113-37050 EXTENSION, FR BUMPER / BR	1.00	43.70		43.70

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due
			

Customer Copy

Inchcape

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no : 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details			
United Overseas Insurance Ltd 146 Robinson Road #02-01 UOI Building Singapore cc			S1000019 / ICUOI1		M/S Eksklusiv Landscape Pte Ltd 1 Bukit Batok Crescent #03-19 Singapore 658064			
			Document No. 0					
			Document Date 06/10/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2021	XZU710R	WKMMV3	21/07/2021	YQ4213R	0	10211	650D/YQ4213R	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JHHUCV3F80K039474		N04CWN14777	60	Francis Cher T S	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
29	9	H82121-37L90 WIRE, ENGINE ✓ BR			1.00	219.60		219.60
Steve (LKK) 8/10/21, 10.00am OD-NH AL EXCISE-? P/P My Bel Sky 10 dys								
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company								
For & on behalf of		Acknowledged by Repairer		Customer's Signature		Charge Summary		Total
Borneo Motors (Singapore) Pte Ltd		Date:		Please acknowledge receipt of vehicle		Parts 7,204.90 Labour 320.00 Sublet 11,080.00 Lubrication/Fluid 0.00 Others 0.00		18,604.90 GST 7.00% 1,302.34 Less 0.00 Amount Due 19,907.24

Customer Copy