



Co. Reg. No.: 201416720C
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883
Tel: 6636 9100 Fax: 6636 9113

Date : 8/10/2021

Cecilia

TO: China Taiping Insurance (Singapore) Pte Ltd
20 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Our Customer : Meenachi D/O
Balasundaram

Vehicle No : SGD6410G

Model : Honda Stream 1.7A

Manufacture Year : 2005 (COE: 20/2/2026)

Date of Accident : 6/10/2021

Total Estimate Repair Days : 5

Total Pages : 2

Attn : Motor Claims Department
Fax : 6224 7478

Re: Repair Estimate For Third Party Claim against SMU5373B

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Rear bumper <i>Rehnd</i>	1	\$760.90	\$760.90	<i>✓ 689</i>
2	Rear bumper side retainer RH <i>Re n</i>	1	\$38.70	\$38.70	<i>+</i>
3	Rear bumper side retainer LH <i>Re n</i>	1	\$38.70	\$38.70	<i>✓</i>
4	Rear fender LH <i>Re n</i>	1	\$965.20	\$965.20	<i>+</i>
5	Rear fender quarter glass moulding LH <i>Re n</i>	1	\$110.90	\$110.90	<i>+</i>
6	Rear knuckle arm LH <i>Damaged</i>	1	\$360.80	\$360.80	<i>✓</i>
7	Rear knuckle arm bearing LH <i>Damaged</i>	1	\$405.90	\$405.90	<i>✓</i>
8	Rear lower arm LH <i>Best</i>	1	\$458.30	\$458.30	<i>✓</i>
	Total			\$1,914.40	
			Less 20%	\$382.88	
	Sub Total 1			\$1,531.52	
A.	Spare Parts (S/Nett)				
1	Reverse sensor (set) <i>Re n</i>	1	\$220.00	\$220.00	<i>+</i>
2	Rear bumper clip <i>Re n</i>	10	\$5.00	\$50.00	<i>30</i>
3	Rear tyre LH <i>Re n</i>	1	\$450.00	\$450.00	<i>+</i>
4	Rear sports rim LH <i>Cut</i>	1	\$550.00	\$550.00	<i>400</i>
5	Sealant <i>Re n</i>	1	\$60.00	\$60.00	<i>+</i>
	Sub-Total 2			\$1,330.00	
	Total for Parts			\$2,861.52	
B.	Labour				
1	To check wiring.			\$40.00	<i>30</i>
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$600.00	<i>400</i>
3	Spray painting all affected parts & areas.			\$600.00	<i>400</i>
4	To spray anti-rust undercoat.			\$30.00	<i>✓</i>
5	To remove and refit rear fender quarter glass.			\$100.00	<i>×</i>
6	To remove and replace undercarriage LH			\$250.00	<i>180</i>
7	To check wheels with computerized wheels alignment.			\$120.00	<i>80</i>
8	To remove and refit rear seats, rear wheelhouse inner garnish, floor carpet & upholstery to facilitate repairs.			\$250.00	<i>60</i>
	Total Labour			\$1,990.00	
	Total Repair Cost			\$4,851.52	



Co. Reg. No.: 201416720C

1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883

Tel : 6636 9100 Fax : 6636 9113

Yours faithfully,

Aun Teng

f Premium Carz Services Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No

Adrian Lj
L/S 11/10/21.
04 Days.

Total: 3172.1688

L/S: 2.5K ✓