

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB21010352/AGS3Q2
Date: 10/12/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SMV5820Y	Insured Vehicle No :	SMW3049R
Date of Loss:	25/09/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0004193

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMV5820Y		
Make & Model:	HONDA FIT, 1.3 (A)	Engine No:	L13B3937104
Reg. Date:	09/10/2020 (Man. Year: 2019)	Chassis No:	GK33422616
Colour:	Silver	Odometer:	6669 km
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	PETLAS 6 mm	Rear Left Side:	PETLAS 6 mm
Front Right Side:	PETLAS 6 mm	Rear Right Side:	PETLAS 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,254.32	659.68	1,594.64	70.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,820.00	680.00	1,140.00	62.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,074.32	1,339.68	2,734.64	67.12
Approved Total (Overridden) (S\$)		1,050.00		

Nett Amount (S\$)	4,074.32	1,050.00	3,024.32	74.23
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	07/10/2021		
Date Inspected:	11/10/2021	Inspected At:	Exclusive Enterprise Pte Ltd (HQ) 8 KAKI BT AV 4#03-50 PREMIER@KB Singapore 415875
Estimated Period of Repair:	3.0 days		

Adjuster:	ADRIAN LING	Manager:	Chong Pui Lin
------------------	-------------	-----------------	---------------

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Dec 2021)
Parts:	144	HONDA FIT 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMV5820Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	716.30 FL	*- FL
2	1		*TAILGATE EMBLEM	Necessary	27.10 FL	*27.10 FL
3	1		*WEATHERSTRIP	Not Necessary	116.20 FL	*- FL
4	1		*REAR BUMPER	Deformed	687.60 FL	*510.00 FL
5	2		*REAR BUMPER SIDE RETAINER L/R	Not Necessary	41.00 FL	*- FL
6	1		*END PANEL	Not Necessary	487.10 FL	*- FL
7	1		*END PANEL TOP GARNISH	Not Necessary	117.60 FL	*- FL
8	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
9	1		*SET END PANEL TOP GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
10	1		*SET REVERSE SENSOR	Damaged	200.00 FS	*200.00 FS
11	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
12	1		*LTA RE-SEAL	Not Necessary	60.00 FS	*- FS
13	1		*W/S SEALANT	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,692.90	767.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	438.58	107.42
Total Parts (\$\$)	2,254.32	659.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R REAR CARPET & TRIMS	New	150.00	0.00
2	R&R REAR W/S	New	120.00	0.00
3	TRANSFER TAILGATE COMPONENT FROM OLD TO NEW	New	100.00	0.00
4	WIRE-CHECK	New	50.00	30.00
5	LABOUR	New	700.00	250.00
6	PAINTING	New	700.00	400.00
Gross Labour Cost (\$\$)			1,820.00	680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >