

Thomas Pang PTCBC

From: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>
Sent: Wednesday, 17 November 2021 4:05 pm
To: Thomas Pang PTCBC
Cc: Asher Sng (LKKAuto)
Subject: Finalize Report GBJ8765Y
Attachments: GBJ 8765 main estimate.pdf; GBJ 8765 supp.pdf; 17112021093621-0001.pdf

CAUTION: This email originated from outside of the organization (Inchcape). Do not click links or open attachments unless you recognise the sender and know the content is safe.

Hi Thomas,

We confirm the finalize \$36,145.30 (P/P, before GST). 20 repair days.

Thanks.

Best Regards,
Steve Chen | Automotive Assessor
LKK Auto Consultants Pte Ltd
Phone: 81117723/6256-3561 | email: stevenfoong@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Thomas Pang PTCBC <Thomas.Pang@borneomotors.com.sg>
Sent: Wednesday, 17 November 2021 9:42 am
To: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>
Subject: Finalize Report GBJ8765Y

Dear Steve,

Attach finalize report for your perusal. 20 working days.

Thank you

Regards

Thomas Pang



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

Steve (LKK)
20/10/21, 2:30pm

WAL AL
18 dgs
P/P
By Bel Sy



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007 / ICLPI1	M/s Lim Kim Hai Electric Co (s) Pte Ltd
	Document No. 0	53 Kallang Place Lim Kim Hai Building Singapore 339177
	Document Date 07/10/2021	Work: 62923711

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	KDH201R	RBDY S5	01/10/2019	GBJ8765Y	0	10329	72/DS/GBJ8765Y

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTFHT02P700249620	1KDB012634	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS:LONPAC INSURANCE TP VEH:GBB2267A DATE OF ACC:01.10.2021				30 100.00
2	S	BP-SUBLET SUPPLY JOINT PANEL SEALANT- FRONT				100 200.00
3	S	BP-SUBLET REPLACE AND REFOCUS HEADLAMP - FRONT				122.40
4	S	BP-SUBLET R/I AC CONDENSOR,PIPING AND REGAS - FRON T				? 360.00
5	S	BP-SUBLET TO RESET ECU AND REPROGRAMME				180.00
6	S	BP-SUBLET REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS - FRONT				1440 3600.00
7	S	BP-SUBLET RESPRAY ACC AFFECTED AREAS - FRONT				1770 3540.00
8	S	BP-SUBLET SUPPLY JOINT PANEL SEALANT- REAR				300 400.00
9	S	BP-SUBLET DRILL HOLE AND INSTALL REVERSE SENSOR - REAR				180.00
10	S	BP-SUBLET CHECK WIRING AND CONDUCT WATER TEST - RE AR				122.40
11	S	BP-SUBLET REMOVE AND TRANSFER TAILGATE COMPONENTS ONTO NEW TAILGATE. R/I REAR REVERSE CAMERA TO FAC REPAIR.				540.00

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
onpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007 / ICLPI1 Document No. 0 Document Date 07/10/2021	M/s Lim Kim Hai Electric Co (s) Pte Ltd 53 Kallang Place Lim Kim Hai Building Singapore 339177 Work: 62923711

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	KDH201R	RBDY S5	01/10/2019	GBJ8765Y	0	10329	72/DS/GBJ8765Y

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTFHT02P700249620	1KDB012634	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	S	BP-SUBLET REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR (photo)				360 720.00
13	S	BP-SUBLET REPLACE TAILGATE GLASS				462.00
14	S	BP-SUBLET REPLACE ACC DAMAGED PARTS 8 x 730 AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS - REAR				5760 7200.00
15	S	BP-SUBLET RESPRAY ACC AFFECTED AREAS - REAR 5 x 590				2950 4720.00
16	L	BP-LPO SUPPLY REGN PLATE (PO#)				50 160.00
17	L	BP-LPO SUPPLY COMPANY DOOR BLACK STICKER				100.00
18	Z	BP-SUNDRY STICKER 70KM/H				25.00
19	1	TREVSE-FMS02 ZGE 2 PT SENSOR FOR HIACE	1.00	56.40		56.40
20	1	T08826-08115 PANEL BONDING AD	1.00	267.20		267.20
21	1	T21000-20 SIKA 182010 SIKA TACK GO! (BLA	2.00	108.00		216.00
22	4	T21000-22 SIKA 207. G+P ADHESIVE PRIMER	1.00	200.00		200.00
23	5	T52119-26651 COVER, FR BUMPER	1.00	546.30		546.30
24	6	S52161-0K040 PIECE,RR BUMPER	10.00	4.10		41.00
25	7	T53112-26070 GRILLE, RADIATOR,	1.00	179.70		179.70
26	8	T52115-26210 SUPPORT, FR BUMPER	1.00	144.60		144.60
27	9	T52116-26210 SUPPORT, FR BUMPER	1.00	144.60		144.60
28	0	T57053-26030 REINFORCE SUB-ASSY,	1.00	154.80		154.80

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors

inchope

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462. Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
.onpac Insurance Berhad 00 Beach Road 19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007 / ICLPI1	M/s Lim Kim Hai Electric Co (s) Pte Ltd 53 Kallang Place Lim Kim Hai Building Singapore 339177 Work: 62923711
	Document No. 0	
	Document Date 07/10/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	KDH201R	RBDY S5	01/10/2019	GBJ8765Y	0	10329	72/DS/GBJ8765Y

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTFHT02P700249620	1KDB012634	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
29	1	T52131-26021 REINFORCEMENT, FR	1.00	361.30		361.30
30	2	T58127-26050 R/F MEMBER CROSS REINFOR	1.00	55.10		55.10
31	3	T53036-26020 L/F MEMBER CROSS REINFOR	1.00	57.30		57.30
32	4	T53111-26500 GRILLE, RADIATOR, (upper)	1.00	223.80		223.80
33	5	T53111-26510 GRILLE, RADIATOR, (lower)	1.00	386.90		386.90
34	6	T53112-26090 GRILLE, RADIATOR, (Back)	1.00	573.90		573.90
35	7	T53301-26080 FRONT BONNET ASSY,	1.00	1030.90		1030.90
36	8	T53803-26011 R/FRT SIDE BRACKET,	1.00	44.50		44.50
37	9	T53410-26041 HINGE ASSY, HOOD, RH	1.00	59.30		59.30
38	0	T53420-26041 HINGE ASSY, HOOD, LH	1.00	59.30		59.30
39	1	T53510-26060 FRONT BONNET LOCK,	1.00	95.00		95.00
40		T53201-26082 SUPPORT SUB-ASSY,	1.00	381.00		381.00
41		T53209-26130 BRACE SUB-ASSY, HOOD	1.00	36.20		36.20
42	4	T57109-26021 REINFORCEMENT	1.00	457.40		457.40
43	5	T90975-02086 TOYOTA SYMBOL EMBLEM,	1.00	72.20		72.20
44	6	T81130-26731 UNIT ASSY, HEADLAMP, (RH)	1.00	753.70		753.70
45	7	T81170-26731 UNIT ASSY, HEADLAMP, (LH)	1.00	753.70		753.70
46	8	T85315-26130 JAR, WASHER, A	1.00	185.20		185.20
47	9	T88450-26120 A/C CONDENSER ASSY,	1.00	1968.30		1968.30
48	0	T16470-75124 RADIATOR RESERVE TANK,	1.00	626.70		626.70

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
onpac Insurance Berhad 00 Beach Road 19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007 / ICLP11	M/s Lim Kim Hai Electric Co (s) Pte Ltd 53 Kallang Place Lim Kim Hai Building Singapore 339177 Work: 62923711
	Document No. 0	
	Document Date 07/10/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
20	KDH201R	RBDY S5	01/10/2019	GBJ8765Y	0	10329	72/DS/GBJ8765Y

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTFHT02P700249620	1KDB012634	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
49	1	T17945-30040 INTERCOOLER BRACKET	1.00	69.90		69.90
50	2	T17940-30051 INTERCOOLER ASSY	1.00	1886.30		1886.30
51	3	T17311-30050 AIR-INLET DUCT NO 1	1.00	114.10		114.10
52	4	T17312-11010 DUCT, AIR INLET,	1.00	74.70		74.70
53	5	T52159-26470 REAR BUMPER COVER, - 00	1.00	458.80		458.80
54	6	T58385-26070 REAR BUMPER BRACKET, - BR	4.00	26.40		105.60
55	7	T52157-26010 R/R SIDE BPR RETAINER, - BR	1.00	23.60		23.60
56	8	T90467-09185 CLIP - PK	6.00	2.90		17.40
57	9	T52155-26150 R/RR BUMPER SUPPORT, - BR	1.00	40.90		40.90
58	0	T52166-26040 A0 L/REAR TOP BUMPER COVER - BR	1.00	95.00		95.00
59	1	T52156-26010 L/RR BUMPER SUPPORT, - BR	1.00	40.90		40.90
60		T90159-60497 SCREW, W/WASHER - PK	6.00	2.20		13.20
61		T57069-26120 REAR OUTER FLR MEMBER, - 00	1.00	346.40		346.40
62	4	T57068-26320 REAR INNER FLR MEMBER, - 00	1.00	1116.70		1116.70
63	5	T57416-26160 RAIL, FLOOR SIDE, RR	1.00	176.80		176.80
64	6	T67935-26190 PLATE, BACK DOOR - BT	1.00	106.90		106.90
65	7	T67936-26040 B1 COVER, BACK DOOR	1.00	12.00		12.00
66	8	T67937-26040 B1 COVER, BACK DOOR	1.00	12.00		12.00
67	9	T61612-26510 L/REAR QUARTER PANEL, - 00	1.00	1562.30		1562.30
68	0	T61706-26230 L/R DOOR FRAME OPENNING, - 00	1.00	576.30		576.30

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors



TOYOTA

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
onpac Insurance Berhad 00 Beach Road 19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007 / ICLP11 Document No. 0 Document Date 07/10/2021	M/s Lim Kim Hai Electric Co (s) Pte Ltd 53 Kallang Place Lim Kim Hai Building Singapore 339177 Work: 62923711

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
20	KDH201R	RBDY S5	01/10/2019	GBJ8765Y	0	10329	72/DS/GBJ8765Y

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTFHT02P700249620	1KDB012634	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
69	1	T61636-26040 REINFORCEMENT	1.00	129.60		129.60
70	2	T61746-26040 REINFORCEMENT, BACK	1.00	292.10		292.10
71	3	T61814-26010 REINFORCEMENT	1.00	44.30		44.30
72	4	T62930-52030 REAR AIR-DUCT ASSY,	1.00	35.20		35.20
73	5	T62632-26300 BOARD, QUARTER TRIM,	1.00	138.60		138.60
74	6	T67771-26230 E0 RETAINER, DOOR TRIM	10.00	5.30		53.00
75	7	T67005-26L50 REAR BACK DOOR PANEL	1.00	2184.00		2184.00
76	8	T67881-26073 RR BACK DOOR W/STRIP,	1.00	412.60		412.60
77	9	T68105-26151 GLASS SUB-ASSY, BACK	1.00	1352.20		1352.20
78	0	T76811-26160 BACK DOOR GARNISH	1.00	144.00		144.00
79	1	T76825-26120 BACK DOOR PROTECTOR	1.00	13.30		13.30
80	2	T67837-26040 SEAL, DOOR DUST	2.00	11.80		23.60
81	3	T67751-26080 BOARD, BACK DOOR	1.00	182.80		182.80
82	4	T67760-26050 B0 BOARD ASSY, BACK	1.00	121.30		121.30
83	5	T69350-26122 REAR BACK DOOR LOCK ASSY,	1.00	279.50		279.50
84	6	T90975-02064 EMBLEM, SYMBOL	1.00	72.20		72.20
85	7	T75441-26281 "TOYOTA HIACE" EMBLEM,	1.00	49.10		49.10
86	8	T81204-26010 LAMP SUB-ASSY,	1.00	118.60		118.60
87	9	T81551-26202 R/R COMBINATION LENS,	1.00	367.60		367.60
88	0	T81561-26201 L/R COMBINATION LENS,	1.00	309.20		309.20

or & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total	46,036.70
	Please acknowledge receipt of vehicle	Parts 23,304.90 Labour 125.00 Sublet 22,606.80 Lubrication/Fluid 0.00 Others 0.00	GST 7.00% Less	3,222.57 0.00
			Amount Due	49,259.27

Customer Copy