

ASSIGNMENT

From:

Date:

Estimated Cost:

OR: TP/WS/TPR/OD/RES/EVA/INV/MV

To inspect Vehicle Not:

at Workshop info:

at:

Insured:

Policy No.:

Claims No.:

Sum Insured:


Excess:

(Client's Record)

Make of Velt:

(Policy Condition)

Remarks: The veh had commenced its repair at the time of inspection.



Ref. or Market Value:

IDAD Accident Report

Consistent? : Yes or No

GIA / PR Sent

Consistent? : Yes or No

Est. Repair:

days

Res.: Yes or No

Sum Sum:

%

3 Vol.: Yes or No

QA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBJ8765Y

Yr Regn:

11/10/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Maker:

Toyota Hiace

CB 2982

Colour:

White

A/O: Insured / Std / NI / N

Sp. Reading:

65743

TIR: Insured / Std / NI / N

Eng/No:

C/No:

TIFHT 028773249620

Gen. Cond: Good / Fair / Poor / Buprt

Steering: Inorder / Jammed / Locked / Burnt or

Brake: Inorder / Jammed / Locked / Burnt or

Mod: Nil / S/Rim / STD / R/Rim or

Tyre Size:

Ft

195R15C

Rt

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

NEXEN

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

11/10/21

D.O.A.

20/12/21

Survey held at

Banana M/strs

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Roof/Top or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MV-77K

Time/Date, File, Remarks:

☐

Procl. Report

☐

Final Report

Time/Date, File, Remarks:

Days Of Repair:

Resurvey No. of Trips:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp

(\$

☐

Interview

(\$

☐

Tech. Insp

(R

☐

Vehicle and

(P

Survey Fee:

Transportation:

Survey Fee:

Transportation:

Inchcape
Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no. 6631 1188

Store (CLKK)
20/10/21, 2:30pm

W/L AL
18 dgs
P/P
By Bel Sy

ESTIMATE

Account Details	Account No.	Customer Details
Lompac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007 / ICLPI1	M/s Lim Kim Hai Electric Co (s) Pte Ltd
	Document No. 0	53 Kallang Place Lim Kim Hai Building Singapore 339177
	Document Date 07/10/2021	Work: 62923711

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	KDH201R	RBDY S5	01/10/2019	GBJ8765Y	0	10329	72/DS/GBJ8765Y

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTFHT02P700249620	1KDB012634	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS:LONPAC INSURANCE TP VEH:GBB2267A DATE OF ACC:01.10.2021				37 100.00
2	S	BP-SUBLET SUPPLY JOINT PANEL SEALANT- FRONT				100 200.00
3	S	BP-SUBLET REPLACE AND REFOCUS HEADLAMP - FRONT				122.40
4	S	BP-SUBLET R/I AC CONDENSOR, PIPING AND REGAS - FRON T				? 360.00
5	S	BP-SUBLET TO RESET ECU AND REPROGRAMME				180.00
6	S	BP-SUBLET REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS - FRONT				1440 3600.00
7	S	BP-SUBLET RESPRAY ACC AFFECTED AREAS - FRONT				1770 3540.00
8	S	BP-SUBLET SUPPLY JOINT PANEL SEALANT- REAR				300 400.00
9	S	BP-SUBLET DRILL HOLE AND INSTALL REVERSE SENSOR - REAR				180.00
10	S	BP-SUBLET CHECK WIRING AND CONDUCT WATER TEST - RE AR				122.40
11	S	BP-SUBLET REMOVE AND TRANSFER TAILGATE COMPONENTS ONTO NEW TAILGATE. R/I REAR REVERSE CAMERA TO FAC REPAIR.				540.00

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no. 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details	
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia		S1000007 / ICLPI1	M/s Lim Kim Hai Electric Co (s) Pte Ltd	
		Document No. 0	53 Kallang Place Lim Kim Hai Building Singapore 339177	
		Document Date 07/10/2021	Work: 62923711	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	KDH201R	RBDY S5	01/10/2019	GBJ8765Y	0	10329	72/DS/GBJ8765Y

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTFHT02P700249620	1KDB012634	60	Thomas Pang W T	--/--/----	0.00 --/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	S	BP-SUBLET REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR (photo)				360 720.00
13	S	BP-SUBLET REPLACE TAILGATE GLASS				462.00
14	S	BP-SUBLET REPLACE ACC DAMAGED PARTS 8 x 710 AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS - REAR				5760 7200.00
15	S	BP-SUBLET RESPRAY ACC AFFECTED AREAS - REAR 5 x 590				2950 4720.00
16	L	BP-LPO SUPPLY REGN PLATE (PO#)				160.00
17	L	BP-LPO SUPPLY COMPANY DOOR BLACK STICKER				100.00
18	Z	BP-SUNDRY STICKER 70KM/H				25.00
19	1	TREVSE-FMS02 ZGE 2 PT SENSOR FOR HIACE	1.00	56.40		56.40
20	2	T08826-08115 PANEL BONDING AD	1.00	267.20		267.20
21	3	T21000-20 SIKI 182010 SIKI TACK GO! (BLA	2.00	108.00		216.00
22	4	T21000-22 SIKI 207. G+P ADHESIVE PRIMER	1.00	200.00		200.00
23	5	T52119-26651 COVER, FR BUMPER	1.00	546.30		546.30
24	6	S52161-0K040 PIECE,RR BUMPER	10.00	4.10		41.00
25	7	T53112-26070 GRILLE, RADIATOR,	1.00	179.70		179.70
26	8	T52115-26210 SUPPORT, FR BUMPER	1.00	144.60		144.60
27	9	T52116-26210 SUPPORT, FR BUMPER	1.00	144.60		144.60
28	0	T57053-26030 REINFORCE SUB-ASSY,	1.00	154.80		154.80

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Sublet	
		Lubrication/Fluid	
		Others	Amount Due

Customer Copy

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details				
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia		S1000007 / ICLPI1	M/s Lim Kim Hai Electric Co (s) Pte Ltd				
		Document No. 0	53 Kallang Place Lim Kim Hai Building Singapore 339177				
		Document Date 07/10/2021	Work: 62923711				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	KDH201R	RBDPY S5	01/10/2019	GBJ8765Y	0	10329	72/DS/GBJ8765Y
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTFHT02P700249620		1KDB012634	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
29	1	T52131-26021 REINFORCEMENT, FR	1.00	361.30		361.30	
30	2	T58127-26050 R/F MEMBER CROSS REINFOR	1.00	55.10		55.10	
31	3	T53036-26020 L/F MEMBER CROSS REINFOR	1.00	57.30		57.30	
32	4	T53111-26500 GRILLE, RADIATOR, (upper)	1.00	223.80		223.80	
33	5	T53111-26510 GRILLE, RADIATOR, (lower)	1.00	386.90		386.90	
34	6	T53112-26090 GRILLE, RADIATOR, (Racing)	1.00	573.90		573.90	
35	7	T53301-26080 FRONT BONNET ASSY, (DB)	1.00	1030.90		1030.90	
36	8	T53803-26011 R/FRT SIDE BRACKET, (DB)	1.00	44.50		44.50	
37	9	T53410-26041 HINGE ASSY, HOOD, RH	1.00	59.30		59.30	
38	0	T53420-26041 HINGE ASSY, HOOD, LH	1.00	59.30		59.30	
39	1	T53510-26060 FRONT BONNET LOCK, (X)	1.00	95.00		95.00	
40	2	T53201-26082 SUPPORT SUB-ASSY, (X)	1.00	381.00		381.00	
41	3	T53209-26130 BRACE SUB-ASSY, HOOD	1.00	36.20		36.20	
42	4	T57109-26021 REINFORCEMENT	1.00	457.40		457.40	
43	5	T90975-02086 TOYOTA SYMBOL EMBLEM, (RH) (BR)	1.00	72.20		72.20	
44	6	T81130-26731 UNIT ASSY, HEADLAMP, (RH) (BR)	1.00	753.70		753.70	
45	7	T81170-26731 UNIT ASSY, HEADLAMP, (LH) (CUT)	1.00	753.70		753.70	
46	8	T85315-26130 JAR, WASHER, A	1.00	185.20		185.20	
47	9	T88450-26120 A/C CONDENSER ASSY, (X)	1.00	1968.30		1968.30	
48	0	T16470-75124 RADIATOR RESERVE TANK, (X)	1.00	626.70		626.70	
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle _____	Parts		Less Amount Due		
			Labour				
			Sublet				
			Lubrication/Fluid				
		Others					

Customer Copy

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no. : 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details					
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia		S1000007 / ICLPI1	M/s Lim Kim Hai Electric Co (s) Pte Ltd 53 Kallang Place Lim Kim Hai Building Singapore 339177 Work: 62923711					
		Document No. 0						
		Document Date 07/10/2021						
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	KDH201R	RBDPY S5	01/10/2019	GBJ8765Y	0	10329	72/DS/GBJ8765Y	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTFHT02P700249620		1KDB012634	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
49	1	T17945-30040	INTERCOOLER BRACKET			1.00	69.90	69.90
50	2	T17940-30051	INTERCOOLER ASSY			1.00	1886.30	1886.30
51	3	T17311-30050	AIR-INLET DUCT NO 1			1.00	114.10	114.10
52	4	T17312-11010	DUCT, AIR INLET			1.00	74.70	74.70
53	5	T52159-26470	REAR BUMPER COVER			1.00	458.80	458.80
54	6	T58385-26070	REAR BUMPER BRACKET			4.00	26.40	105.60
55	7	T52157-26010	R/R SIDE BPR RETAINER			1.00	23.60	23.60
56	8	T90467-09185	CLIP			6.00	2.90	17.40
57	9	T52155-26150	R/RR BUMPER SUPPORT			1.00	40.90	40.90
58	0	T52166-26040 A0	L/REAR TOP BUMPER COVER			1.00	95.00	95.00
59	1	T52156-26010	L/RR BUMPER SUPPORT			1.00	40.90	40.90
60	2	T90159-60497	SCREW, W/WASHER			6.00	2.20	13.20
61	3	T57069-26120	REAR OUTER FLR MEMBER			1.00	346.40	346.40
62	4	T57068-26320	REAR INNER FLR MEMBER			1.00	1116.70	1116.70
63	5	T57416-26160	RAIL, FLOOR SIDE, RR			1.00	176.80	176.80
64	6	T67935-26190	PLATE, BACK DOOR			1.00	106.90	106.90
65	7	T67936-26040 B1	COVER, BACK DOOR			1.00	12.00	12.00
66	8	T67937-26040 B1	COVER, BACK DOOR			1.00	12.00	12.00
67	9	T61612-26510	L/REAR QUARTER PANEL			1.00	1562.30	1562.30
68	0	T61706-26230	L/R DOOR FRAME OPENNING			1.00	576.30	576.30
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts		Less		
				Labour				
				Sublet				
				Lubrication/Fluid		Amount Due		
				Others				

Customer Copy

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no. 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details			
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia			S1000007 / ICLPI1		M/s Lim Kim Hai Electric Co (s) Pte Ltd 53 Kallang Place Lim Kim Hai Building Singapore 339177 Work: 62923711			
			Document No.					
			0					
			Document Date					
07/10/2021								
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	KDH201R	RBDPY S5	01/10/2019	GBJ8765Y	0	10329	72/DS/GBJ8765Y	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTFHT02P700249620		1KDB012634	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
69	1	T61636-26040	REINFORCEMENT	1.00	129.60		129.60	
70	2	T61746-26040	REINFORCEMENT, BACK	1.00	292.10		292.10	
71	3	T61814-26010	REINFORCEMENT	1.00	44.30		44.30	
72	4	T62930-52030	REAR AIR-DUCT ASSY,	1.00	35.20		35.20	
73	5	T62632-26300	BOARD, QUARTER TRIM,	1.00	138.60		138.60	
74	6	T67771-26230 E0	RETAINER, DOOR TRIM	10.00	5.30		53.00	
75	7	T67005-26L50	REAR BACK DOOR PANEL	1.00	2184.00		2184.00	
76	8	T67881-26073	RR BACK DOOR W/STRIP,	1.00	412.60		412.60	
77	9	T68105-26151	GLASS SUB-ASSY, BACK	1.00	1352.20		1352.20	
78	0	T76811-26160	BACK DOOR GARNISH	1.00	144.00		144.00	
79	1	T76825-26120	BACK DOOR PROTECTOR	1.00	13.30		13.30	
80	2	T67837-26040	SEAL, DOOR DUST	2.00	11.80		23.60	
81	3	T67751-26080	BOARD, BACK DOOR	1.00	182.80		182.80	
82	4	T67760-26050 B0	BOARD ASSY, BACK	1.00	121.30		121.30	
83	5	T69350-26122	REAR BACK DOOR LOCK ASSY,	1.00	279.50		279.50	
84	6	T90975-02064	EMBLEM, SYMBOL	1.00	72.20		72.20	
85	7	T75441-26281	"TOYOTA HIACE" EMBLEM,	1.00	49.10		49.10	
86	8	T81204-26010	LAMP SUB-ASSY,	1.00	118.60		118.60	
87	9	T81551-26202	R/R COMBINATION LENS,	1.00	367.60		367.60	
88	0	T81561-26201	L/R COMBINATION LENS,	1.00	309.20		309.20	
For & on behalf of			Customer's Signature	Charge Summary		Total		46,036.70
Borneo Motors (Singapore) Pte Ltd						Total		46,036.70
Please acknowledge receipt of vehicle					GST 7.00%		3,222.57	
LKK Auto Consultants hence notify the Repairer of the following:			Parts 23,304.90		Less		0.00	
• Labour before/after spray painting			Labour 125.00		Amount Due		49,259.27	
• Paint during resurvey			Sublet 22,606.80					
• Third party			Lubrication/Fluid 0.00					
• No illegal modification			Others 0.00					
• Supplementary Rental is subject to final approval from insurance company								
Acknowledged by Repairer			Customer Copy					
Signature:								
Date:								