

ASSIGNMENT

From:

Date:

Estimated Cost:

OR: TP/RS/PR/REG/OD/RES/EVA/INV/MV

To inspect Vehicle Not:

at Workshop info:

at:

Insured:

Policy No.:

Claims No.:

Sum Insured:


Excess:

(Client's Record)

Make of Velt:

(Policy Condition)

Remarks: The veh had commenced its repair at the time of inspection.



Ref. or Market Value:

IDAD Accident Report

Consistent? : Yes or No

GIA / PR Sent

Consistent? : Yes or No

Est. Repair:

days

Res.: Yes or No

Sum Sum:

%

3 Vol.: Yes or No

QA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBJ8765Y

Yr Regn:

11/10/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Maker:

Toyota Hiace

C.B.

2982

Colour:

White

A/O: Insured / Std / NI / N

Sp. Reading

65743

TIR: Insured / Std / NI / N

Eng/No:

C/No:

TIFHT 028773249620

Gen. Cond: Good / Fair / Poor / Brupt

Steering: Inorder / Jammed / Locked / Burnt or

Brake: Inorder / Jammed / Locked / Burnt or

Mod: Nil / S/Rim / STD / R/Rim or

Tyre Size:

195R15C

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

NEXEN

Front

Rear

R/Bal.

5 mm

mm

R/Bal.

5 mm

L/Bal.

5 mm

mm

L/Bal.

5 mm

D.O.A.

11/10/21

D.O.I.

20/12/21

Survey held at

Banana M/strs

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Roof/Top or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

MV-77K

Time / File / Remarks

☐

Procl. Report

☐

Final Report

Time / File / Remarks

Days Of Repair:

Resurvey No. of Trips

Survey Fee:

Transportation

Add Fee:

☐

Site Insp

(\$

☐

Interview

(\$

☐

Tech. Insp

(R

☐

Vehicle

(R

Survey Fee:

Transportation

Survey Fee:

Transportation

Inchcape

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no. 6631 1188

Store (CLKK)
 20/10/21, 2:30pm

20 # dgs

P/P

By Bel Sy

ESTIMATE

Account Details	Account No.	Customer Details
Lompac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007 / ICLPI1	M/s Lim Kim Hai Electric Co (s) Pte Ltd
	Document No. 0	53 Kallang Place Lim Kim Hai Building Singapore 339177
	Document Date 07/10/2021	Work: 62923711

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	KDH201R	RBDY S5	01/10/2019	GBJ8765Y	0	10329	72/DS/GBJ8765Y
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTFHT02P700249620	1KDB012634	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS:LONPAC INSURANCE TP VEH:GBB2267A DATE OF ACC:01.10.2021				377 - 100.00
2	S	BP-SUBLET SUPPLY JOINT PANEL SEALANT- FRONT				100 200.00
3	S	BP-SUBLET REPLACE AND REFOCUS HEADLAMP - FRONT				122.40
4	S	BP-SUBLET R/I AC CONDENSOR, PIPING AND REGAS - FRON T				8 360.00
5	S	BP-SUBLET TO RESET ECU AND REPROGRAMME				180.00
6	S	BP-SUBLET REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS - FRONT 3 ± dgs - 779				2160 - 1440 3600.00
7	S	BP-SUBLET RESPRAY ACC AFFECTED AREAS - FRONT				590 x 3 4 3540.00
8	S	BP-SUBLET SUPPLY JOINT PANEL SEALANT- REAR				1360 / 1770 300 400.00
9	S	BP-SUBLET DRILL HOLE AND INSTALL REVERSE SENSOR - REAR				180.00
10	S	BP-SUBLET CHECK WIRING AND CONDUCT WATER TEST - RE AR				122.40
11	S	BP-SUBLET REMOVE AND TRANSFER TAILGATE COMPONENTS ONTO NEW TAILGATE. R/I REAR REVERSE CAMERA TO FAC REPAIR.				540.00

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy

hchc000

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no. 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details	
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia		S1000007 / ICLPI1	M/s Lim Kim Hai Electric Co (s) Pte Ltd	
		Document No. 0	53 Kallang Place Lim Kim Hai Building Singapore 339177	
		Document Date 07/10/2021	Work: 62923711	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	KDH201R	RBDY S5	01/10/2019	GBJ8765Y	0	10329	72/DS/GBJ8765Y

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTFHT02P700249620	1KDB012634	60	Thomas Pang W T	--/--/----	0.00 --/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	S	BP-SUBLET REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR (photo)				360 720.00
13	S	BP-SUBLET REPLACE TAILGATE GLASS				462.00
14	S	BP-SUBLET REPLACE ACC DAMAGED PARTS 98 x 710 AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS - REAR				6480 5760 7200.00
15	S	BP-SUBLET RESPRAY ACC AFFECTED AREAS - REAR 6J x 590				3540 2950 4720.00
16	L	BP-LPO SUPPLY REGN PLATE (PO#)				80 160.00
17	L	BP-LPO SUPPLY COMPANY DOOR BLACK STICKER				50 100.00
18	Z	BP-SUNDRY STICKER 70KM/H				25.00
19	1	TREVESE-FMS02 ZGE 2 PT SENSOR FOR HIACE	1.00	56.40		56.40
20	2	T08826-08115 PANEL BONDING AD	1.00	267.20		267.20
21	3	T21000-20 SIKI 182010 SIKI TACK GO! (BLA	2.00	108.00		216.00
22	4	T21000-22 SIKI 207. G+P ADHESIVE PRIMER	1.00	200.00		200.00
23	5	T52119-26651 COVER, FR BUMPER	1.00	546.30		546.30
24	6	S52161-0K040 PIECE,RR BUMPER	10.00	4.10		41.00
25	7	T53112-26070 GRILLE, RADIATOR,	1.00	179.70		179.70
26	8	T52115-26210 SUPPORT, FR BUMPER	1.00	144.60		144.60
27	9	T52116-26210 SUPPORT, FR BUMPER	1.00	144.60		144.60
28	0	T57053-26030 REINFORCE SUB-ASSY,	1.00	154.80		154.80

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Sublet	
		Lubrication/Fluid	
		Others	
			Amount Due

Customer Copy

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details				
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia		S1000007 / ICLPI1	M/s Lim Kim Hai Electric Co (s) Pte Ltd				
		Document No. 0	53 Kallang Place Lim Kim Hai Building Singapore 339177				
		Document Date 07/10/2021	Work: 62923711				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	KDH201R	RBDPY S5	01/10/2019	GBJ8765Y	0	10329	72/DS/GBJ8765Y
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTFHT02P700249620	1KDB012634	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
29	1	T52131-26021 REINFORCEMENT, FR	1.00	361.30			361.30
30	2	T58127-26050 R/F MEMBER CROSS REINFOR	1.00	55.10		bt	55.10
31	3	T53036-26020 L/F MEMBER CROSS REINFOR	1.00	57.30		bt	57.30
32	4	T53111-26500 GRILLE, RADIATOR, (upper)	1.00	223.80			223.80
33	5	T53111-26510 GRILLE, RADIATOR, (lower)	1.00	386.90			386.90
34	6	T53112-26090 GRILLE, RADIATOR, (Racing)	1.00	573.90		bt	573.90
35	7	T53301-26080 FRONT BONNET ASSY,	1.00	1030.90			1030.90
36	8	T53803-26011 R/FRT SIDE BRACKET,	1.00	44.50			44.50
37	9	T53410-26041 HINGE ASSY, HOOD, RH	1.00	59.30			59.30
38	0	T53420-26041 HINGE ASSY, HOOD, LH	1.00	59.30			59.30
39	1	T53510-26060 FRONT BONNET LOCK,	1.00	95.00			95.00
40	2	T53201-26082 SUPPORT SUB-ASSY,	1.00	381.00		bt	381.00
41	3	T53209-26130 BRACE SUB-ASSY, HOOD	1.00	36.20		bt	36.20
42	4	T57109-26021 REINFORCEMENT	1.00	457.40		br	457.40
43	5	T90975-02086 TOYOTA SYMBOL EMBLEM,	1.00	72.20			72.20
44	6	T81130-26731 UNIT ASSY, HEADLAMP, (RH)	1.00	753.70			753.70
45	7	T81170-26731 UNIT ASSY, HEADLAMP, (LH)	1.00	753.70			753.70
46	8	T85315-26130 JAR, WASHER, A	1.00	185.20			185.20
47	9	T88450-26120 A/C CONDENSER ASSY,	1.00	1968.30		br	1968.30
48	0	T16470-75124 RADIATOR RESERVE TANK,	1.00	626.70			626.70
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle	Parts		Less		
			Labour				
			Sublet				
			Lubrication/Fluid				
		Others		Amount Due			

Customer Copy

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no. : 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details				
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia		S1000007 / ICLPI1	M/s Lim Kim Hai Electric Co (s) Pte Ltd 53 Kallang Place Lim Kim Hai Building Singapore 339177 Work: 62923711				
		Document No. 0					
		Document Date 07/10/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	KDH201R	RBDPY S5	01/10/2019	GBJ8765Y	0	10329	72/DS/GBJ8765Y
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTFHT02P700249620	1KDB012634	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
49	1	T17945-30040 INTERCOOLER BRACKET	1.00	69.90		69.90	
50	2	T17940-30051 INTERCOOLER ASSY	1.00	1886.30		1886.30	
51	3	T17311-30050 AIR-INLET DUCT NO 1	1.00	114.10		114.10	
52	4	T17312-11010 DUCT, AIR INLET	1.00	74.70		74.70	
53	5	T52159-26470 REAR BUMPER COVER	1.00	458.80		458.80	
54	6	T58385-26070 REAR BUMPER BRACKET	4.00	26.40		105.60	
55	7	T52157-26010 R/R SIDE BPR RETAINER	1.00	23.60		23.60	
56	8	T90467-09185 CLIP	6.00	2.90		17.40	
57	9	T52155-26150 R/RR BUMPER SUPPORT	1.00	40.90		40.90	
58	0	T52166-26040 A0 L/REAR TOP BUMPER COVER	1.00	95.00		95.00	
59	1	T52156-26010 L/RR BUMPER SUPPORT	1.00	40.90		40.90	
60	2	T90159-60497 SCREW, W/WASHER	2	6.60		13.20	
61	3	T57069-26120 REAR OUTER FLR MEMBER	1.00	346.40		346.40	
62	4	T57068-26320 REAR INNER FLR MEMBER	1.00	1116.70		1116.70	
63	5	T57416-26160 RAIL, FLOOR SIDE, RR	1.00	176.80		176.80	
64	6	T67935-26190 PLATE, BACK DOOR	1.00	106.90		106.90	
65	7	T67936-26040 B1 COVER, BACK DOOR	1.00	12.00		12.00	
66	8	T67937-26040 B1 COVER, BACK DOOR	1.00	12.00		12.00	
67	9	T61612-26510 L/REAR QUARTER PANEL	1.00	1562.30		1562.30	
68	0	T61706-26230 L/R DOOR FRAME OPENNING	1.00	576.30		576.30	
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle	Parts		Less		
			Labour				
			Sublet				
			Lubrication/Fluid		Amount Due		
			Others				

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007 / ICLPI1	M/s Lim Kim Hai Electric Co (s) Pte Ltd 53 Kallang Place Lim Kim Hai Building Singapore 339177 Work: 62923711
	Document No. 0	
	Document Date 17/11/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	KDH201R	RBDY S5	01/10/2019	GBJ8765Y	0	10329	72/DS/GBJ8765Y

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTFHT02P700249620	1KDB012634	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	1	T90159-60497 SCREW, W/WASHER	4.00	2.20		8.80
2	2	S08889-80102 COOLANT,SLLC&&&	2.00	80.30		160.60
3	3	T68810-26011 HINGE ASSY,BACK	1.00	68.70		68.70
4	4	T68820-26011 HINGE ASSY,BACK	1.00	68.70		68.70
5	5	T90189-06034 GROMMET	2.00	2.50		5.00
6	6	T90189-06057 GROMMET	6.00	2.70		16.20
7	7	T52158-26010 SUPPORT,RR BUMPER	1.00	23.60		23.60
8	8	T62930-52030 DUCT ASSY, QUARTER	1.00	35.20		35.20

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total	386.80
	Please acknowledge receipt of vehicle	Parts 386.80	GST 7.00%	27.08
		Labour 0.00	Less	0.00
		Sublet 0.00		
		Lubrication/Fluid 0.00		
		Others 0.00	Amount Due	413.88

Customer Copy