



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia			S1000007 / ICLPI1		M/s Lim Kim Hai Electric Co (s) Pte Ltd 53 Kallang Place Lim Kim Hai Building Singapore 339177 Work: 62923711		
			Document No. 0				
			Document Date 17/11/2021				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	KDH201R	RBPDY S5	01/10/2019	GBJ8765Y	0	10329	72/DS/GBJ8765Y
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTFHT02P700249620		1KDB012634	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY TP INS:LONPAC INSURANCE TP VEH:GBB2267A DATE OF ACC:01.10.2021 BY:LKK-STEVE @ 20.10.2021 20 WORKING DAYS				30.00	
2	S	BP-SUBLET SUPPLY JOINT PANEL SEALANT- FRONT				200.00	
3	S	BP-SUBLET REPLACE AND REFOCUS HEADLAMP - FRONT				122.40	
4	S	BP-SUBLET R/I AC CONDENSOR,PIPING AND REGAS - FRON T				360.00	
5	S	BP-SUBLET TO RESET ECU AND REPROGRAMME				180.00	
6	S	BP-SUBLET REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS - FRONT				2160.00	
7	S	BP-SUBLET RESPRAY ACC AFFECTED AREAS - FRONT				2360.00	
8	S	BP-SUBLET SUPPLY JOINT PANEL SEALANT- REAR				300.00	
9	S	BP-SUBLET DRILL HOLE AND INSTALL REVERSE SENSOR - REAR				180.00	
10	S	BP-SUBLET CHECK WIRING AND CONDUCT WATER TEST - RE AR				122.40	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
					Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007 / ICLP11	M/s Lim Kim Hai Electric Co (s) Pte Ltd 53 Kallang Place Lim Kim Hai Building Singapore 339177 Work: 62923711
	Document No. 0	
	Document Date 17/11/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	KDH201R	RBP DY S5	01/10/2019	GBJ8765Y	0	10329	72/DS/GBJ8765Y

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTFHT02P700249620	1KDB012634	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
11	S	BP-SUBLET REMOVE AND TRANSFER TAILGATE COMPONENTS ONTO NEW TAILGATE.				540.00
12	S	R/I REAR REVERSE CAMERA TO FAC REPAIR.				
12	S	BP-SUBLET REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR				360.00
13	S	BP-SUBLET REPLACE TAILGATE GLASS				462.00
14	S	BP-SUBLET REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS - REAR				6480.00
15	S	BP-SUBLET RESPRAY ACC AFFECTED AREAS - REAR				3540.00
16	L	BP-LPO SUPPLY REGN PLATE (PO#)				80.00
17	L	BP-LPO SUPPLY COMPANY DOOR BLACK STICKER				50.00
18	Z	BP-SUNDRY STICKER 70KM/H				25.00
19	1	TREVSE-FMS02 ZGE 2 PT SENSOR FOR HIACE	1.00	56.40		56.40
20	2	T08826-08115 PANEL BONDING AD	1.00	267.20		267.20
21	3	T21000-20 SIKI 210002-0 TACK GO! (BLACK) SG	2.00	108.00		216.00
22	4	T21000-22 SIKI 210002-2 G+P 207 ADHESIVE PRIMER	1.00	200.00		200.00
23	5	T52119-26651 COVER, FR BUMPER	1.00	546.30		546.30
24	6	S52161-0K040 PIECE, RR BUMPER	10.00	4.10		41.00
25	7	T53111-26500 GRILLE, RADIATOR,	1.00	223.80		223.80

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Sublet	
		Lubrication/Fluid	
		Others	
			Less
			Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details				Account No.		Customer Details			
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia				S1000007 / ICLPI1		M/s Lim Kim Hai Electric Co (s) Pte Ltd 53 Kallang Place Lim Kim Hai Building Singapore 339177 Work: 62923711			
				Document No.					
				0					
				Document Date					
				17/11/2021					

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	KDH201R	RBDY S5	01/10/2019	GBJ8765Y	0	10329	72/DS/GBJ8765Y

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTFHT02P700249620	1KDB012634	60	Thomas Pang W T	--/--/----	0.00 --/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
26	8	T53111-26510 GRILLE, RADIATOR,	1.00	386.90		br 386.90
27	9	T53301-26080 HOOD SUB-ASSY	1.00	1030.90		dd 1030.90
28	0	T90975-02086 EMBLEM,SYMBOL	1.00	72.20		nec 72.20
29	1	T81130-26731 UNIT ASSY, HEADLAMP,	1.00	753.70		br 753.70
30	2	T81170-26731 UNIT ASSY, HEADLAMP,	1.00	753.70		cut 753.70
31	3	T52159-26470 COVER,RR BUMPER	1.00	458.80		dd 458.80
32	4	T58385-26070 BRACKET, RR BUMPER	4.00	26.40		br 105.60
33	5	T52157-26010 SUPPORT,RR BUMPER	1.00	23.60		br 23.60
34	6	T90467-09185 CLIP	6.00	2.90		nec 17.40
35	7	T52155-26150 SUPPORT,RR BUMPER RH	1.00	40.90		br 40.90
36	8	T52166-26040 A0 L/REAR TOP BUMPER COVER	1.00	95.00		br 95.00
37	9	T52156-26010 SUPPORT,RR BUMPER LH	1.00	40.90		br 40.90
38	0	T90159-60497 SCREW, W/WASHER	2.00	2.20		nec 4.40
39	1	T57069-26120 MEMBER SUB-ASSY,RR	1.00	346.40		dd 346.40
40	2	T57068-26320 MEMBER SUB-ASSY,RR	1.00	1116.70		dd 1116.70
41	3	T67935-26190 PLATE,BACK DOOR	1.00	106.90		bt 106.90
42	4	T61612-26510 PANEL, QUARTER	1.00	1562.30		dd 1562.30
43	5	T61706-26230 L/R DOOR FRAME OPENN	1.00	576.30		dd 576.30
44	6	T61636-26040 REINFORCEMENT	1.00	129.60		dd 129.60
45	7	T67005-26L50 BACK DOOR PANEL W/CAMERA	1.00	2184.00		dd 2184.00

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Sublet	
		Lubrication/Fluid	
		Others	Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007 / ICLPI1	M/s Lim Kim Hai Electric Co (s) Pte Ltd
	Document No. 0	53 Kallang Place Lim Kim Hai Building Singapore 339177
	Document Date 17/11/2021	Work: 62923711

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	KDH201R	RBP DY S5	01/10/2019	GBJ8765Y	0	10329	72/DS/GBJ8765Y

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTFHT02P700249620	1KDB012634	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
46	8	T68105-26151 GLASS SUB-ASSY, BACK	1.00	1352.20		br 1352.20
47	9	T76811-26160 BACK DOOR GARNISH	1.00	144.00		cut 144.00
48	0	T76825-26120 BACK DOOR PROTECTOR	1.00	13.30		nec 13.30
49	1	T67837-26040 SEAL, DOOR DUST	2.00	11.80		nec 23.60
50	2	T67751-26080 BOARD, BACK DOOR	1.00	182.80		cru 182.80
51	3	T69350-26122 LOCK ASSY, BACK DOOR	1.00	279.50		bt 279.50
52	4	T90975-02064 EMBLEM, SYMBOL	1.00	72.20		nec 72.20
53	5	T75441-26281 PLATE, LUGGAGE	1.00	49.10		nec 49.10
54	6	T81561-26201 LENS, RR COMB LH	1.00	309.20		br 309.20
55	7	T90159-60497 SCREW, W/WASHER	4.00	2.20		nec 8.80
56	8	T57053-26030 REINFORCE SUB-ASSY,	1.00	154.80		bt 154.80
57	9	T58127-26050 R/F MEMBER CROSS REINFOR	1.00	55.10		bt 55.10
58	0	T53036-26020 L/F MEMBER CROSS REINFOR	1.00	57.30		bt 57.30
59	1	T53209-26130 BRACE SUB-ASSY, HOOD	1.00	36.20		bt 36.20
60	2	T57109-26021 REINFORCEMENT	1.00	457.40		br 457.40
61	3	T88450-26120 CONDENSER ASSY	1.00	1968.30		br 1968.30
62	4	T61746-26040 REINFORCEMENT, BACK	1.00	292.10		bt 292.10
63	5	T62930-52030 DUCT ASSY, QUARTER	1.00	35.20		cra 35.20
64	6	T67881-26073 WEATHERSTRIP, BACK DR	1.00	412.60		cra 412.60
65	7	S08889-80102 COOLANT, SLLC&&&	2.00	80.30		cra 160.60

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details				Account No.		Customer Details			
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia				S1000007 / ICLPI1		M/s Lim Kim Hai Electric Co (s) Pte Ltd 53 Kallang Place Lim Kim Hai Building Singapore 339177 Work: 62923711			
				Document No.					
				0					
				Document Date					
				17/11/2021					

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	KDH201R	RBDY S5	01/10/2019	GBJ8765Y	0	10329	72/DS/GBJ8765Y

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTFHT02P700249620	1KDB012634	60	Thomas Pang W T	--/--/----	0.00 --/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
66	8	T68810-26011 HINGE ASSY,BACK	1.00	68.70		bt 68.70
67	9	T68820-26011 HINGE ASSY,BACK	1.00	68.70		bt 68.70
68	0	T90189-06034 GROMMET	2.00	2.50		nec 5.00
69	1	T90189-06057 GROMMET	6.00	2.70		nec 16.20
70	2	T53201-26082 SUPPORT SUB-ASSY,	1.00	381.00		bt 381.00
71	3	T53112-26090 GRILLE, RADIATOR,	1.00	573.90		cra 573.90
72	4	T52158-26010 SUPPORT,RR BUMPER	1.00	23.60		br 23.60
73	5	T62930-52030 DUCT ASSY, QUARTER	1.00	35.20		br 35.20

For & on behalf of		Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd						36,145.30	
		Please acknowledge receipt of vehicle		Parts 18,593.50		GST 7.00% 2,530.17	
				Labour 55.00			
				Sublet 17,496.80		Less 0.00	
				Lubrication/Fluid 0.00			
				Others 0.00		Amount Due 38,675.47	

Customer Copy