



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2200823

3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV Date 15/02/2022  
Reference CC3/CTI21010357/Kra3q2  
Code CTI

### PROFESSIONAL SERVICE FEE

Vehicle No. SHB 7969D  
Insured Veh. SMY 7701D  
Claim No. SNM21D205670/LKKDS  
Policy No. DMPCSNW0006132100  
Accident Date 01/10/2021  
Inspection Date 05/10/2021

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI21010357/Kra3q2	
			Date: 15/02/2022	
			Code: CTI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SMY 7701D	Veh. Inspected	SHB 7969D	
Policy No.	DMPCSNW0006132100	Coverage (\$)	0.00	
Claim No.	SNM21D205670/LKKDS	Excess (\$)	0.00	
Assign From		Assign Date	05/10/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA PRIUS (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	JTDKB3FU203091995	Colour	M . P. WHITE / RED	
Odometer	84264 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	SAILUN	9 mm	
L/H Front Tyre	195/65 R15	SAILUN	9 mm	
R/H Rear Tyre	195/65 R15	DUNLOP	2 mm	
L/H Rear Tyre	195/65 R15	DUNLOP	2 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	01/10/2021	Inspection Date	05/10/2021	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>2 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 7969D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	COVER REAR BUMPER	BUCKLED	485.60	485.60
1	REINFORCEMENT SUB-ASSY ,REAR BUMPER	BENT	332.70	332.70
1	GUARD REAR BUMPER ,CENTER	BENT	374.50	374.50
1	COVER ,REAR BUMPER ,LOWER	SERVICEABLE	22.00	-
1	RETAINER ,REAR BUMPER SIDE ,LH	NO SUCH PARTS	132.60	-
1	RETAINER ,REAR BUMPER SIDE ,RH	NO SUCH PARTS	132.60	-
1	REFLECTOR ASSY ,REFLEX LH	NO SUCH PARTS	132.60	-
1	REFLECTOR ASSY ,REFLEX ,LH	SERVICEABLE	39.00	-
1	PANEL SUB-ASSY ,BODY LOWER BACK	TO REPAIR SEE LABOUR	651.00	-
1	COVER ,DECK TRIM ,REAR	SERVICEABLE	126.70	-
1	COVER ,FLOOR UNDER NO.2 (RH)	SERVICEABLE	241.90	-
1	COVER ,FLOOR UNDER NO.1 (LH)	SERVICEABLE	175.10	-
1	COVER ,REAR FLOOR (CTR)	SERVICEABLE	229.90	-
	LESS 25% DISCOUNT		-769.05	-298.20
			2,307.15	894.60
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	85.00	50.00
1	REAR NUMBER PLATE WITH MOULDING (SN)	SERVICEABLE	200.00	-
1	REAR FLOOR UNDERCOVER CLIP (SN)	NOT NECESSARY	180.00	-
1	REAR SPOILER CLIP (SN)	NOT NECESSARY	70.00	-
1	BUMPER CENTRE GUARD CLIP (SN)	NOT NECESSARY	80.00	-
1	REAR BUMPER PROTECTOR (SN)	NECESSARY	180.00	40.00
1	REAR BUMPER RETAINER CLIP (SN)	NOT NECESSARY	75.00	-
			1,570.00	90.00
<b><u>LABOUR</u></b>				
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.	NOT NECESSARY	240.00	-



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY ,BODY LOWER BACK .		1,600.00	200.00
	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION .		1,600.00	220.00
	TO REINSTALL REAR BUMPER PARKING SENSOR .		170.00	50.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.	NOT NECESSARY	170.00	-
			4,540.00	470.00
<b>GRAND TOTAL</b>			<b>8,417.15</b>	<b>1,454.60</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>1,454.60</b>

Report Ref No. CC3/CTI21010357/Kra3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SHB 7969D

### INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SHB 7969D

### RE-INSPECTION

