

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB7969D**

Vehicle No.:  
Chassis No.:  
Vehicle Make:  
Vehicle Model:  
Date of Accident :  
Third Party Insurer :  
Date of Registration:

05 OCT 2021

AAD2109-

*Not Authored**Presurvey B4 paint**81454.60***SHB7969D**

JTDKB3FU203091995

TOYOTA

PRIUS GEN 4

01/10/2021

**CHINA**

30/09/2020

- |   | <b>PART</b>                         |
|---|-------------------------------------|
| 1 | COVER, REAR BUMPER                  |
| 1 | REINFORCEMENT SUB-ASSY, REAR BUMPER |
| 1 | GUARD, REAR BUMPER, CENTER          |
| 1 | COVER, REAR BUMPER, LOWER           |
| 1 | RETAINER, REAR BUMPER SIDE, LH      |
| 1 | RETAINER, REAR BUMPER SIDE, RH      |
| 1 | REFLECTOR ASSY, REFLEX, LH          |
| 1 | PANEL SUB-ASSY, BODY LOWER BACK     |
| 1 | COVER, DECK TRIM, REAR              |
| 1 | COVER, FLOOR UNDER, NO.2 (RH)       |
| 1 | COVER, FLOOR UNDER, NO.1 (LH)       |
| 1 | COVER, REAR FLOOR (CTR)             |

LIST	
\$	Buc 485.60 <i>✓</i>
\$	B4 332.70 <i>✓</i>
\$	B4 374.50 <i>✓</i>
\$	Sm 22.00 X
\$	NIP 132.60 X
\$	NIP 132.60 X
\$	Sm 39.00 X
\$	R 651.00 X
\$	Sm 126.70 X
\$	Sm 241.90 X
\$	Sm 175.10 X
\$	Sm 229.90 X
TOTAL \$	2,943.60
25% \$	735.90
\$	2,207.70

**Special Nett**

- 1SET PARKING AID  
1SET REAR BUMPER CLIP  
1 REAR NUMBER PLATE WITH MOULDING  
1 REAR FLOOR UNDERCOVER CLIP  
1 REAR SPOILER CLIP  
1 BUMPER CENTRE GUARD CLIP  
1 REAR BUMPER PROTECTOR  
1 REAR BUMPER RETAINER CLIP

\$	Sm 700.00 X
\$	Sm 85.00 <i>505m ✓</i>
\$	Sm 200.00 X
\$	nn 180.00 X
\$	nn 70.00 X
\$	nn 80.00 X
\$	Rec 180.00 <i>405m ✓</i>
\$	nn 75.00 X

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB7969D****AAD2109-**

<b>TOTAL</b>	<b>\$</b>	<b>1,570.00</b>
<b>TOTAL PARTS</b>	<b>\$</b>	<b>3,777.70</b>

**LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ *nn* 240.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,600.00 *200*

To transfer of rear end panel fittings, attachment to facilitate bodywork repair.

\$ *nn* 380.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 1,600.00 *220*

To reinstall rear bumper parking sensor.

\$ 170.00 *50*

To Check Electrical Lighting Concerned.

\$ *nn* 170.00 X

**TOTAL** **\$** **4,540.00**

**Over All Total** **\$** **8,317.70**

**(PART-BY-PART) Repair Days**

**10 Days**

*2 day*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: