



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE)SINGAPORE 417883 ON BEHALF OF GOLD FORTE PTE LTD			Ref: CS/TP21010358/Uuf3e2 Date: 19/10/2021 Code: TP149	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b>	<b>Veh. Inspected</b>	SMP 3575A	
	<b>Policy No.</b>	<b>Coverage (\$)</b>	0.00	
	<b>Claim No.</b>	<b>Excess (\$)</b>	0.00	
	<b>Assign From</b>	<b>Assign Date</b>	08/10/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	TOYOTA NOAH HYBRID (A)	<b>c.c</b>	1797
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2019
	<b>Chassis No.</b>	ZWR800388603	<b>Colour</b>	BLACK
	<b>Odometer</b>	157591 KM	<b>Steering</b>	AFFECTED
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
	<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	195/65 R15	SAILWIN	6 mm
	<b>L/H Front Tyre</b>	195/65 R15	SAILWIN	6 mm
	<b>R/H Rear Tyre</b>	195/65 R15	FIRENZA	6 mm
	<b>L/H Rear Tyre</b>	195/65 R15	KUMHO	6 mm
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
	<b>Accident Date</b>	06/10/2021	<b>Inspection Date</b>	08/10/2021
	<b>Survey held at</b>	BLUWEL RENT-A CAR PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-56 AUTOBAY @KAKI BUKIT SINGAPORE 417883		
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>6 Working Days</b>	