

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: *SMF3575A*at Workshop m/s *Blue cont-a-car*

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: *£110k*

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: *6* days Res.: Yes or NoLum Sum: *20* % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: *LTA 550833*

Vehicle: IN / OUT

Date / Time

Action / Instruction

Repair.

18/10/13 *1/5 @ 9000 confirmed w/b AH Seen* 6 repair days
(RED \$6047.05; 40%)

Veh No: *SMF3575A* Yr Regn: *23/9/19*Type: *M/Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or *CA*Make: *Toyota Noah Hybrid* C.C. *1797*Colour: *black* A/C: Insured / Std / NI / NASp. Reading: *157591* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *ZWR 800388603*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *in order* / Jammed / Leaked / Burnt or *affected*Brake: *in order* / Jammed / Leaked / Burnt orModi: Nil / *SRM* / STD A/Rim orTyre Size: F: *195/65 R15*R: *Finants*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *Sa. / win*

Front

Rear

R/Bal. *6* mm R/Bal. *6* mmL/Bal. *6* mm L/Bal. *6* *kumho* mmD.O.A. *6/10/21* D.O.I. *8/10/21*

Survey held at _____

Des. of Damages: *Frt* / Rear / O/S / N/S / U/C / Rooftop orThe *1/5* Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1) 18/10 TYPIST

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: *6*Resurvey No. of Trip: *2*

Survey Fee:

Transportation:

Add Fee: ☐ Site Insp (\$)) *S* + RS, *SI*☐ Interview (\$)

) Photos

☐ Tech. Invs (\$)

) Others

☐ Weekend (\$)

)

Report Format: TP

Lump Sum *110k* (\$ 9000)

TOTAL

BLUWEL RENT-A-CAR PTE LTD
1 KAKI BUKIT AVE 6 BLK C # 01-56
SINGAPORE 417883

not followed
Kaka
8/10/17
1/58 9000
6 days.

VEHICLE No: SMP 3575A

1PC	BONNET	Bent/Buc	\$871.10	—
1PC	BONNET OUTER CHROME	twi/cne	\$561.60	—
2PCS	BONNET HINGES @ \$171.25	R	\$342.50	X
1PC	FRONT GRILLE TOP	cne	\$571.75	—
1PC	FRONT GRILLE BOTTOM	cne	\$561.80	—
1PC	FRONT BUMPER	Dis	\$1,288.20	—
2PCS	FRONT BUMPER SIDE RETAINERS @ \$145.20	cne/nel	\$290.40	—
1PC	FRONT BUMPER LOWER CENTRE GRILLE	Dis/twi	\$371.75	—
1PC	FRONT BUMPER UNDER COVER	Dis	\$381.90	—
1PC	FRONT BUMPER FOG LAMP COVER N/S	Dis	\$271.10	—
1PC	FRONT BUMPER SPONGE	Torn	\$189.90	—
1PC	FRONT BUMPER REINFORCEMENT	Bent	\$371.25	—
1PC	HEADLAMP N/S	cne	\$2,584.40	—
1PC	HEADLAMP OUTER BLACK GARNISH N/S	cw	\$122.10	—
1PC	HEADLAMP TOP PANEL N/S	Bent	\$271.45	—
1PC	FRONT SUPPORT PANEL	R	\$1,218.10	X
1PC	FRONT FENDER N/S	Bent/Buc	\$731.55	—
1PC	FRONT FENDER INNER SHIELD N/S	Torn	\$182.10	—
2PCS	FRONT FENDER 'HYBRIDS' EMBLEM @ \$121.10	nel	\$242.20	—
1PC	FRONT FENDER INNER PANEL N/S	R	\$192.80	X
1PC	FRONT FENDER INNER SIDE FRT PANEL N/S	Bent	\$699.10	—
1PC	FRONT KNUCKLE ARM N/S	11	\$561.25	X
1PC	FRONT KNUCKLE ARM BEARING N/S	11	\$251.10	X
			\$13,129.40	
			LESS 25%	\$9,847.05

S.NETT

1SET	FRONT GRILLE CLIPS	nel	\$50.00	—
1SET	FRONT BUMPER CLIPS	nel	\$50.00	—
1SET	FRONT BUMPER UNDER COVER CLIPS	nel	\$50.00	—
1PC	FRONT SPORT RIM N/S	cw	\$800.00	500
1PC	FRONT TYRE N/S	Buc	\$200.00	X
1SET	FRONT FENDER INNER SHIELD CLIPS N/S	nel	\$50.00	—
1SET	FRONT FENDER ACCESSORIES EMBLEM LH& RH	nel	\$150.00	—

TO CHECK WIRING	\$50.00	30
TO REFILL AIR CON GAS	11	\$120.00 X
TO RESET & REPROGRAMME DIAGNOSIS SYSTEM		\$180.00/00
TO CONDUCT WHEEL ALIGNMENT		\$120.00 80
TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	11	\$180.00 X
TO SPRAY RUST PROOFING		\$100.00 80

LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

\$1,300.00 900
\$1,800.00 1300
TOTAL \$15,047.05

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

10563.65
352
9-792273
S.N - 810
A - 2490