

⏪	<	1 of 2 ?	>	⏩	↺	↻	100% ▼	📄 ✓	🖨	<input type="text"/> Find Next
---	---	----------	---	---	---	---	--------	-----	---	----------------------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSES SINGAPORE 068877			Ref: CS3/FCI21010359/Vvf3 Date: 08/10/2021 Code: FCI2	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	GBD 1049J		Veh. Inspected	SMY 6209R
Policy No.			Coverage (\$)	0.00
Claim No.	D21002807MFCV		Excess (\$)	0.00
Assign From	SITHARA		Assign Date	08/10/2021
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
Accident Date	22/09/2021		Inspection Date	12/10/2021
Survey held at	SIN SENG HONG SPRAY PAINTING & SERVICES BLK 3022A UBI ROAD 1 #01-53 . SINGAPORE 408716			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				