

Borneo Motors



scope

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No.2 Pandan Crescent
Singapore 128462, Tel no.: 6631 1388

Steve (LKK)

11/10/21, 1032

WHL PL
7 dji

P/P

My Bal My

LKK

Summer

+60197356879

11/10 - 10am.

ESTIMATE

Account Details			Account No.		Customer Details			
Lompac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia			S1000007 / ICLPI1		Mr Tan Lay Hai			
			Document No. 0		52 New Upper Changi Road #13-1486 Singapore 461052			
			Document Date 07/10/2021		Mobile: 91802425			
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	AVV60R	BEXGB S5	18/01/2018	SLV8363S	0	20227	61TP/SLV8363S/061021	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTHBW1GG402181753		2AR1878569	60	Carine Yeo C L	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P INS: LONPAC INS ACC DATE: 06.10.2021 T/P VEH: XE3720A DATE IN: DATE SURVEY: DATE AUTHORIZE:						50 / 100.00
2	B	BP-LAB3 TO REMOVE ALL NECESSARY PARTS TO ENABLE REPAIRING AND STRAIGHTEN ON FRONT BUMPER, BONNET, FRONT SUPPORT, RHS FRONT FENDER, FRONT DOOR, REAR DOOR AND FIX NEW PARTS 3-5 x 866						3031 / 6062.00
3	B	BP-RES3 TO SPRAY PAINT ON WHOLE FRONT PORTION INCL FRONT SUPPORT AND BOTH RHS DOORS 4 x 742						2968 / 5936.00
4	B	BP-LAB3 TO REMOVE AND RE-INSTALL AIR COND CONDENSER, RADIATOR ETC TO ENABLE REPAIR (NETT) X 2						866.00
5	B	BP-LAB3 TO REMOVE AND REPLACE RHS HEADLAMP. CHECK AND FOCUS HEADLIGHTS (NETT)						216.50
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd						Less		
LKK Auto Consultants		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Amount Due		
the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a 'Without Prejudice' basis • No illegal modification(s) is allowed • Supplementary fee(s) must be displayed and is subject to final approval from insurance Company								
Acknowledged by Repairer Signature: Date:								

Customer Copy

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No.2 Pandan Crescent
Singapore 128462, Tel no: 6631 1388

ESTIMATE

Account Details			Account No.		Customer Details		
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia			S1000007 / ICLPI1		Mr Tan Lay Hai 52 New Upper Changi Road #13-1486 Singapore 461052 Mobile: 91802425		
			Document No. 0				
			Document Date 07/10/2021				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	AVV60R	BEXGB S5	18/01/2018	SLV8363S	0	20227	61TP/SLV8363S/061021
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTHBW1GG402181753		2AR1878569	60	Carine Yeo C L	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
6	B	BP-LAB3 TO REMOVE AND TRANSFER FRONT PARKING SENSOR TO ENABLE REPAIR (NETT)					216.50 ✓
7	Z	BP-SLANT SUPPLY BONNET SEALANT (NETT)					100.00 ✓
8	Z	BP-SLANT SUPPLY FRONT SUPPORT SEALANT (NETT)					100.00 X
9	B	BP-LAB3 TO REMOVE, RENEW AND BALANCE RHS FRONT TYRE AND RIM (NETT)					108.25 X
10	B	BP-LAB3 TO CARRY OUT WHEEL ALIGNMENT <i>To Reset ECU And Reprogramming</i>					216.50 X
11	S	BP-SUBLET SUPPLY RHS FRONT TYRE					800.00 X
12	T	BP-MISC1 SHOULD THE ABOVE VEHICLE BE SUBJECT TO TOTAL LOSS OR TOW OUT BY INSURANCE COMPANY OR BY THE OWNER PRIOR TO THE REPAIR A 6% OF THE QUOTATION PRICE WILL BE IMPOSED AS ADMIN CHARGES TO A MAX OF \$1000 + TOWING CHARGES IF APPLICABLE.					
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Customer Copy

inchope

Co. Reg No. : 1967000862
GST Reg No. : MR-8500000-9
No 2 Pandan Crescent
Singapore 128462, Tel no. 6631 1388

ESTIMATE


Account Details			Account No.		Customer Details		
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia			S1000007 / ICLP11		Mr Tan Lay Hai 52 New Upper Changi Road #13-1486 Singapore 461052 Mobile: 91802425		
			Document No. 0				
			Document Date 07/10/2021				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	AVV60R	BEXGB S5	18/01/2018	SLV8363S	0	20227	61TP/SLV8363S/061021
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTHBW1GG402181753		2AR1878569	60	Carine Yeo C L	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
13	Z	BP-MISC2 A DAILY STORAGE CHARGE AT THE RATE OF S\$25/- PER DAY WILL COMMENCE 7 DAYS AFTER ESTIMATE DATE. THESE CHGS WILL NOT APPLY IF REPAIRS ARE UNDERTAKEN BY BORNEO MOTORS.					
14	1	L52119-3T910 COVER, FR BUMPER	1.00	968.20		968.20	
15	2	L52125-33120 BRACKET, FOG LAMP	1.00	170.10		170.10	
16	3	L52145-33070 STAY, FR BUMPER	1.00	58.00		58.00	
17	4	L52197-30040 BUMPER BRACKET,	2.00	7.80		15.60	
18	5	L52611-33280 ABSORBER, FR BUMPER	1.00	155.90		155.90	
19	6	L53155-33060 SEAL, RADIATOR	1.00	101.50		101.50	
20	7	L53879-30040 RETAINER, FR FENDER	2.00	12.40		24.80	
21	8	L81481-33060 COVER, FOG LAMP, RH	1.00	143.30		143.30	
22	9	L52021-33210 REINFORCEMENT	1.00	504.10		504.10	
23	0	L53301-33160 HOOD SUB-ASSY	1.00	2273.20		2273.20	
24	1	L53381-33100 SEAL,HOOD TO	1.00	49.80		49.80	
25	2	L53811-33230 FENDER,FR RH	1.00	1353.20		1353.20	
26	3	L53827-33070 PROTECTOR, FR FENDER	1.00	101.50		101.50	
27	4	L53835-33100 BRACE,FR FENDER TO	1.00	72.00		72.00	
28	5	L53837-33010 BRACKET, FR SIDE	2.00	20.70		41.40	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Customer Copy

inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No 2 Pandan Crescent
Singapore 128462, Tel no. 6631 1388

ESTIMATE

Account Details			Account No.		Customer Details			
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia			S1000007 / ICLP11		Mr Tan Lay Hai 52 New Upper Changi Road #13-1486 Singapore 461052 Mobile: 91802425			
			Document No.					
			0					
			Document Date					
			07/10/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	AVV60R	BEXGB S5	18/01/2018	SLV8363S	0	20227	61TP/SLV8363S/061021	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTHBW1GG402181753		2AR1878569	60	Carine Yeo C L	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
29	6	T90467-07214 CLIP <i>nec</i>			12.00	2.70		32.40
30	7	L53875-33220 LINER,FR FENDER RH <i>TN</i>			1.00	281.10		281.10
31	8	L51441-33200 COVER, ENGINE UNDER, <i>X</i>			1.00	234.20		234.20
32	9	L53201-33191 SUPPORT,RADIATOR <i>X</i>			1.00	1468.00		1468.00
33	0	L53208-33070 SUPPORT SUB-ASSY, <i>X</i>			1.00	153.60		153.60
34	1	T90467-07217 CLIP <i>nec</i>			9.00	2.60		23.40
35	2	L53295-33080 SEAL,COOL AIR <i>X</i>			1.00	305.70		305.70
36	3	L85315-33461 JAR, WASHER, A <i>X</i>			1.00	276.10		276.10
37	4	L89341-78010 C1 SENSOR, ULTRASONIC, <i>X</i>			2.00	490.80		981.60
38	5	L89341-78010 B2 SENSOR, ULTRASONIC, <i>X</i>			2.00	490.80		981.60
39	6	L89348-35030 CLIP, ULTRASONIC <i>nec</i>			2.00	4.40		8.80
40	7	L89348-76010 CLIP, ULTRASONIC <i>nec</i>			2.00	12.10		24.20
41	8	L81210-48051 LAMP ASSY,FOG RH <i>X</i>			1.00	516.00		516.00
42	9	L81105-33D11 HOUSING SUB-ASSY, <i>BR (HeadLp)</i>			1.00	6185.20		6185.20
43	0	L75535-33020 MOULDING,WINDSHIELD RH <i>X</i>			1.00	87.30		87.30
44	1	L75545-30170 CLIP,WINDSHIELD <i>nec</i>			10.00	10.70		107.00
45	2	L75547-51021 ROOF DRIP MLDG CLIP, <i>nec</i>			10.00	11.00		110.00
46	3	L53111-33450 GRILLE, RADIATOR <i>X</i>			1.00	1180.90		1180.90
47	4	L53121-33080 MOULDING, RADIATOR <i>X</i>			1.00	375.80		375.80
48	5	L42611-33B61 WHEEL, DISC <i>X</i>			1.00	2760.50		2760.50
For & on behalf of			Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd							36,847.75	
			Please acknowledge receipt of vehicle		Parts		22,126.00	
					Labour		13,921.75	
					Sublet		800.00	
					Lubrication/Fluid		0.00	
					Others		0.00	
					GST 7.00%		2,579.34	
					Less		0.00	
					Amount Due		39,427.09	

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No.2 Pandan Crescent
Singapore 189702
Singapore 128462, Tel no.: 6631 1388



ESTIMATE

Account Details	Account No.	Customer Details
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007 / ICLP11	Mr Tan Lay Hai 52 New Upper Changi Road #13-1486 Singapore 461052 Mobile: 91802425
	Document No. 0	
	Document Date 21/10/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	AVV60R	BEXGB S5	18/01/2018	SLV8363S	0	20265	61SU/SLV8363S
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTHBW1GG402181753	2AR1878569	60	Carine Yeo C L	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUPPLEMENTARY ESTIMATE POLICY NO.: ACC DATE: TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				
2	B	BP-ECU3 TO RESET ECU AND REPROGRAMME (NETT)				216.50

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total	216.50	
	Please acknowledge receipt of vehicle	Parts	0.00	GST 7.00%	15.16
		Labour	216.50	Less	0.00
		Sublet	0.00		
		Lubrication/Fluid	0.00		
		Others	0.00	Amount Due	231.66

Customer Copy