

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0823/2021/JT
DATE : 6-Oct-21
WIP : 47801

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 7/10/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR MOK CHENG HAO
ADDRESS : 596D ANG MO KIO ST 52
#21-309
SINGAPORE 564596
TELEPHONE : HP +65 81333977
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210058191
VEHICLE NO : **SNA 2870 X**
MODEL CODE : AUDI A3 SB 1.5 TFSI S
MODEL YEAR : 15/6/2021
ENGINE NO : DFY 267218
CHASSIS NO : WAUZZZGY7MA095411
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 5-Oct-21
PLACE OF ACCIDENT : BLK 596D MULTI-STOREY
CARPARK

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 2870 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	250
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00	500
4	TO RESPRAY FRONT BUMPER AND BONNET. ^{550 550 300} _{lower spoiler}	\$ 2,000.00	1400
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 5,002.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 2870 X

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Repair</i>	1	\$ 1,574.00	X	
2	FRONT BUMPER FIXING PARTS <i>3 are new</i>	1	\$ 281.00	X	
3	FRONT BUMPER CLOSING ELEMENT - RH	1	\$ 116.00	X	
4	FRONT BUMPER GRILLE <i>cracked</i>	1	\$ 387.00	✓	
5	FRONT BUMPER CLOSING ELEMENT - CENTER <i>new</i>	1	\$ 237.00	X	
6	FRONT BUMPER AIR GUIDE - RH <i>new</i>	1	\$ 60.00	X	
7	FRONT BUMPER SPOILER <i>Repair</i>	1	\$ 292.00	X	
8	FRONT BUMPER COVER TRIM - RH <i>nt</i>	1	\$ 93.00	✓	
9	FRONT BUMPER AIR GUIDE GRILLE - RH <i>new</i>	1	\$ 153.00	X.	
10	FRONT BUMPER SUPPORT - RH ?	1	\$ 38.00	?	
11	FRONT RADIATOR GRILLE <i>cracked</i>	1	\$ 842.00	✓	
12	FRONT RADIATOR CLOSING ELEMENT ?	1	\$ 152.00	?	
13	FRONT REINFORCEMENT FILLER FOAM ?	1	\$ 107.00	?	
14	FRONT BUMPER CARRIER ?	1	\$ 703.00	?	
15	FRONT BUMPER TOP COVER <i>new</i>	1	\$ 82.00	X	
16	FRONT BUMPER SUPPORT - LH / RH ?	2	\$ 18.00	?	
17	CAUTION STICKER	1	\$ 14.00	X	
18	AIR-CONDITIONER STICKER	1	\$ 8.00	X	
19	HORN	1	\$ 145.00	X	
20	HORN BRACKET - RH	1	\$ 31.00	X.	
SUB TOTAL SPARE PARTS			\$ 5,333.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 2870 X

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BONNET <i>Repis</i>	1	\$ 2,664.00	x
22	FRONT BONNET IMPACT PROTECTION	1	\$ 27.00	x
23	FRONT BONNET STRIKER - RH	1	\$ 110.00	x
24	FRONT BONNET LOCK	1	\$ 214.00	x
25	FRONT HEADLIGHT - RH <i>cut</i>	1	\$ 3,840.00	✓
26	FRONT HEADLIGHT CYLINDER	1	\$ 193.00	x
27	FRONT HEADLIGHT WASHER HOSE	1	\$ 93.00	x
28	FRONT RADIATOR AIR GUIDE - RH	1	\$ 36.00	x
29	FRONT RADIATOR AIR GUIDE - CENTER	1	\$ 52.00	x
30	FRONT RADIATOR SEAL	1	\$ 13.00	x
32	FRONT TEMPERATURE SENSOR BRACKET	1	\$ 19.00	x
33	SUNDRIES ?	1	\$ 300.00	?
34	FRONT NO PLATE <i>Dented</i>	S/N	\$ 60.00	✓
TOTAL SPARE PARTS		:	\$ 12,954.00	
TOTAL LABOUR CHARGES		:	\$ 5,002.00	
GRAND TOTAL		:	\$ 17,956.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian Ling.
SURVEYED DATE : 07/10/21
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 04 Days.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT