

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0823/2021/JT
DATE : 06-Oct-21
WIP : 47801

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 7/10/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

4 days - ok - Jy - 18 Nov 21

OWNER'S NAME : MR MOK CHENG HAO
ADDRESS : 596D ANG MO KIO ST 52
#21-309
SINGAPORE 564596
TELEPHONE : HP +65 81333977
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210058191
VEHICLE NO : **SNA 2870 X**
MODEL CODE : AUDI A3 SB 1.5 TFSI S
MODEL YEAR : 15/06/2021
ENGINE NO : DFY 267218
CHASSIS NO : WAUZZZGY7MA095411
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 05-Oct-21
PLACE OF ACCIDENT : BLK 596D MULTI-STOREY
CARPARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 2870 X

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	\$ 250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,100.00	\$ 500.00
4	TO RESPRAY FRONT BUMPER AND BONNET.	\$	2,000.00	\$ 1,400.00
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 5,002.00	\$ 2,342.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 2870 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 1,574.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 281.00	
3	FRONT BUMPER CLOSING ELEMENT - RH	1	\$ 116.00	
4	FRONT BUMPER GRILLE	1	\$ 387.00	\$ 309.60
5	FRONT BUMPER CLOSING ELEMENT - CENTER	1	\$ 237.00	
6	FRONT BUMPER AIR GUIDE - RH	1	\$ 60.00	
7	FRONT BUMPER SPOLIER	1	\$ 292.00	
8	FRONT BUMPER COVER TRIM - RH	1	\$ 93.00	\$ 74.08
9	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 153.00	
10	FRONT BUMPER SUPPORT - RH	1	\$ 38.00	
11	FRONT RADIATOR GRILLE	1	\$ 842.00	\$ 673.20
12	FRONT RADIATOR CLOSING ELEMENT	1	\$ 152.00	\$ 121.60
13	FRONT REINFORCEMENT FILLER FOAM	1	\$ 107.00	\$ 85.60
14	FRONT BUMPER CARRIER	1	\$ 703.00	
15	FRONT BUMPER TOP COVER	1	\$ 82.00	
16	FRONT BUMPER SUPPORT - LH / RH	2	\$ 18.00	
17	CAUTION STICKER	1	\$ 14.00	
18	AIR-CONDITIONER STICKER	1	\$ 8.00	
19	HORN	1	\$ 145.00	
20	HORN BRACKET - RH	1	\$ 31.00	
SUB TOTAL SPARE PARTS		:	\$ 5,333.00	\$ 1,264.08

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 2870 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 1,264.08
21	FRONT BONNET	1 \$	2,664.00	
22	FRONT BONNET IMPACT PROTECTION	1 \$	27.00	
23	FRONT BONNET STRIKER - RH	1 \$	110.00	
24	FRONT BONNET LOCK	1 \$	214.00	
25	FRONT HEADLIGHT - RH	1 \$	3,840.00	\$ 3,072.00
26	FRONT HEADLIGHT CYLINDER	1 \$	193.00	
27	FRONT HEADLIGHT WASHER HOSE	1 \$	93.00	
28	FRONT RADIATOR AIR GUIDE - RH	1 \$	36.00	
29	FRONT RADIATOR AIR GUIDE - CENTER	1 \$	52.00	
30	FRONT RADIATOR SEAL	1 \$	13.00	
32	FRONT TEMPERATURE SENSOR BRACKET	1 \$	19.00	
33	SUNDRIES	1 \$	300.00	
34	FRONT NO PLATE	S/N \$	60.00	\$ 60.00
TOTAL SPARE PARTS		:	\$ 12,954.00	\$ 4,396.08
TOTAL LABOUR CHARGES		:	\$ 5,002.00	\$ 2,342.00
GRAND TOTAL		:	\$ 17,956.00	\$ 6,738.08

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-15/11/21