

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0819/2021/JT
DATE : 5-Oct-21
WIP : 47686

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON TBC

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

3 days - ok - Johnny Boo

10-Nov-21

OWNER'S NAME : MR TAN YI QIANG NICHOLAS
ADDRESS : 3 JALAM HARUM
SINGAPORE 268477
TELEPHONE : HP +65 98801721
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100472638-05
VEHICLE NO : **SLD9321B**
MODEL CODE : AUDI A1 SB TFSI S
MODEL YEAR : 6/30/2015
ENGINE NO : CHZ 093498
CHASSIS NO : WAUZZZ8X2GB103256
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 5-Oct-21
PLACE OF ACCIDENT : JUNCTION OF GRANGE ROAD
AND ORCHARD BOUVELARD

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLD 9321 B

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEDLIGHT WASHER ASSY.	S/N \$	360.00	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	700.00	
3	TO RENEW AND REINSTALL AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$	1,400.00	
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,200.00	\$ 1,000.00
5	TO RESPRAY FRONT BUMPER AND BONNET.	\$	2,000.00	\$ 1,100.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$	8,852.00	\$ 2,292.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLD 9321 B

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 1,634.00	\$	1,307.20
2	FRONT BUMPER FIXING PARTS	1	\$ 248.00		
3	FRONT BUMPER ADAPTER - LH / RH	2	\$ 34.00		
4	FRONT BUMPER GRILLE - CENTER	1	\$ 196.00		
5	FRONT BUMPER CLOSING ELEMENT	1	\$ 167.00		
6	FRONT BUMPER AIR GRILLE - LH / RH	2	\$ 808.00		
7	RADIATOR GRILLE	1	\$ 970.00	\$	775.60
8	FRONT BUMPER FORM PIECE	1	\$ 118.00		
9	FRONT BUMPER REINFORCEMENT	1	\$ 723.00		
10	FRONT BUMPER BRACKET	1	\$ 19.00		
11	HORN - LH / RH	2	\$ 452.00		
12	BONNET	1	\$ 2,261.00	\$	1,808.80
13	BONNET ATTACHMENT PARTS	1	\$ 139.00		
14	BONNET EDGE PROTECTION	1	\$ 20.00	\$	15.92
15	BONNET UPPER CATCH	1	\$ 66.00		
16	BONNET STRIKER	2	\$ 100.00		
17	BONNET LOWER CATCH	1	\$ 63.00		
18	BONNET LOCK	2	\$ 427.00		
19	BONNET BOWDEN CABLE - CENTER	1	\$ 58.00		
20	BONNET BOWDEN CABLE COVER	1	\$ 10.00		
SUB TOTAL SPARE PARTS		:	\$ 8,513.00	\$	3,907.52

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLD 9321 B

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY		S/NETT	REMARKS
		<i>c/f</i>		\$	3,907.52
21	HEADLIGHT MOUNTING - LH / RH	2	\$	236.00	
22	HEADLIGHT - LH / RH	2	\$	3,906.00	
23	A/C STICKER	1	\$	38.00	\$ 29.84
24	CAUTION STICKER	1	\$	14.00	\$ 10.88
25	LOCK CARRIER	1	\$	1,024.00	
26	A/C CONDENSER	1	\$	551.00	
27	COOLANT	6	\$	142.00	
28	RADIATOR AIR GUIDE - LH / RH	2	\$	62.00	
29	FRONT NO. PLATE	S/N	\$	60.00	\$ 60.00
30	SUNDRIES		\$	350.00	
TOTAL SPARE PARTS		:	\$	14,896.00	\$ 4,008.24
TOTAL LABOUR CHARGES		:	\$	8,852.00	\$ 2,292.00
GRAND TOTAL		:	\$	23,748.00	\$ 6,300.24

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-10/11/21

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT