

Not Authash
 11 days &
 Repair After Paint
 21 days



Seah Jin Ji Kenneth
 Blk 117A Jalan Tentern #20-505
 Singapore 321117

File No : SH/2021/082/10/003/TP
 Date : 16-October-2021

Estimated cost of repair for vehicle no : SMD373Z Hyundai Elantra
 Accident involving vehicle no: SMD373Z & SMQ9328C on 30.09.2021

Description	Quantity	Cost Price	
Bonnet	1	\$ Bu 1,526.00	/
RH Bonnet hinge	1	\$ R 69.60	/
LH Bonnet hinge	1	\$ L 69.60	/
Bonnet lock	1	\$ B 129.90	/
RH head lamp	1	\$ R 1,198.90	/
LH head lamp	1	\$ L 1,198.90	/
RH head lamp bracket	1	\$ R 48.00	/
LH head lamp bracket	1	\$ nec 48.00	/
Front grille	1	\$ CM 550.30	/
Front grille clips (1 set)	1	\$ R 18.00	/
Front grille emblem	1	\$ R 58.00	/
RH front fender	1	\$ Bu 434.30	/
RH front fender wheel cowling	1	\$ SVC 98.20	X
Front fender wheel cowling clips (1 set)	1	\$ SVC 28.00	X
Front bumper	1	\$ T 443.90	/
Front bumper clips (1 set)	1	\$ R 35.00	/
Front bumper sponge	1	\$ SVC 110.70	X
Front bumper reinforcement upper	1	\$ SVC 695.80	X
Front bumper reinforcement lower	1	\$ 395.00	X DT
Front bumper tow cover	1	\$ SVC 38.00	X
RH Front bumper fog lamp	1	\$ R 195.00	X
RH Front bumper fog lamp cover	1	\$ SVC 120.00	X
RH Front bumper retainer	1	\$ CM 28.70	/
LH Front bumper retainer	1	\$ CM 28.70	/
RH Front bumper bracket	1	\$ nec 48.80	/
LH Front bumper bracket	1	\$ nec 48.80	/
Front support panel	1	\$ CM 979.50	/
Front support panel top garnish	1	\$ CM 125.00	/
Front support panel top garnish clips (1 set)	1	\$ R 24.00	/
Air con condensor	1	\$ SVC 680.00	X
Air con condensor pipe inlet	1	\$ SVC 325.20	X
Air con condensor pipe outlet	1	\$ SVC 298.40	X
RH Air con condensor air guide	1	\$ SVC 96.80	X
LH Air con condensor air guide	1	\$ SVC 96.80	X
Radiator	1	\$ SVC 810.50	X
Radiator auto fan	1	\$ SVC 597.50	X
Radiator spare tank	1	\$ cra 165.00	/
Engine air cleaner	1	\$ nn 395.00	X
Engine air cleaner front air duct	1	\$ R 98.80	/
		\$ 12,356.60	

		\$	12,356.60	
Rear boot	1	\$	B ₁ 1,782.00	✓
RH Rear boot hinge	1	\$	B ₁ 94.30	✓
LH Rear boot hinge	1	\$	B ₁ 94.30	✓
Rear boot emblem	1	\$	nn 38.00	✓
RH Rear boot number plate lamp	1	\$	CM 70.00	✓
LH Rear boot number plate lamp	1	\$	CM 70.00	✓
RH Rear boot inner tail lamp	1	\$	CM 298.80	✓
LH Rear boot inner tail lamp	1	\$	CM 298.80	✓
Rear boot badge "Elantra"	1	\$	nn 48.00	✓
Rear boot badge "S"	1	\$	nn 35.00	✓
Rear boot inner lock	1	\$	nn 158.40	✓
Rear boot weatherstrip	1	\$	Disired 99.30	✓
Rear boot inner trim board	1	\$	Return 120.00	✓
Rear boot inner trim board clips (1set)	1	\$	nn 22.00	✓
RH outer tail lamp	1	\$	CM 380.00	✓
LH outer tail lamp	1	\$	CM 380.00	✓
RH outer tail lamp panel	1	\$	B ₁ 170.50	✓
LH outer tail lamp panel	1	\$	B ₁ 170.50	✓
RH rear fender	1	\$	B ₁ 1,768.30	✓
LH rear fender	1	\$	R 1,768.30	x
Rear windscreen moulding	1	\$	nn 82.60	✓
Rear bumper	1	\$	B ₁ 459.40	✓
Rear bumper clips (1 set)	1	\$	nn 28.00	✓
Rear bumper reinforcement	1	\$	B ₁ 480.00	✓
RH Rear bumper retainer	1	\$	CM 44.30	✓
LH Rear bumper retainer	1	\$	nn 44.30	x
RH Rear bumper bracket	1	\$	CM 38.80	✓
LH Rear bumper bracket	1	\$	CM 38.80	✓
Rear bumper keyless sensor	1	\$	CM 289.00	✓
Rear bumper lower moulding	1	\$	B ₁ 250.10	✓
RH Rear bumper reflector	1	\$	nn 40.80	x
LH Rear bumper reflector	1	\$	CM 40.80	✓
RH Rear bumper dust cover	1	\$	nn 38.00	✓
LH Rear bumper dust cover	1	\$	nn 38.00	x
Rear end panel	1	\$	B ₁ 454.60	✓
Rear end panel top trim	1	\$	nn 83.40	✓
Rear cargo floor panel	1	\$	R 585.00	x
Rear cargo floor panel top board trim	1	\$	cra 380.20	✓
RH rear cargo inner trim	1	\$	Return 385.00	✓
LH rear cargo inner trim	1	\$	nn 385.00	✓
		\$	24,409.20	
		Less 10%	\$ 2,440.92	
		\$	21,968.28	

Rear boot reverse camera		\$	21,968.28	
Front number plate	1	S. nett	\$ 380.00	✓
Rear number plate	1	S. nett	\$ 45.00	✓
Rear parking sensors (1 set)	1	S. nett	\$ 45.00	✓
Engine coolant	1	S. nett	\$ 260.00	200ml ✓
Rear windscreen sealant	1	S. nett	\$ 30.00	✓
Rear windscreen inner rubber seal	1	S. nett	\$ 60.00	40ml ✓
Towing Charge	1	S. nett	\$ 28.00	✓
To remove and check air con condenser, dryer, aluminium pipes, valves and reinstall components and vacuum and charge refrigerant R134a and check for leakage and full functionality		\$	60.00	50l
To remove front damaged parts, to jack out front support panel, front body, and cut out damaged parts, to straighten out front chassis, to reweld, reshape and repair bonnet hinge panel, LH front fender and inner panel, head lamp inner panel, front support panel, front chassis member, RH & LH front doors, to replace damaged parts and adjust body panel alignment		\$	120.00	100l
To spray paint affected front and inner damaged portion inclusive of preparatory works and material		\$	880.00	600l
To remove and reinstall rear windscreen and conduct water leak test		\$	1,250.00	1100l
To remove rear damaged parts, to jack out rear end panel and rear floor panel and cut out body panel, to reweld, reshape and repair RH and LH rear fenders, rear end panel, rear floor panel, rear body panel, to straighten out rear chassis member, to replace damaged parts and adjust rear body and tailgate alignment		\$	120.00	✓
To spray paint affected rear and inner damaged portion inclusive of preparatory works and material		\$	1,100.00	1000l
To apply anti-corrosion Tuff-Kote		\$	1,300.00	1200l
To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp		\$	150.00	✓
To perform computer diagnostic on drivetrain, ABS systems, parking system, headlamp systems, and clear fault codes		\$	45.00	4cl
		\$	150.00	×

27,991.28

T/Party: AIG Asia Pacific Insurance Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Workshop: 160 Sin Ming Drive #07-02, Sin Ming Auto City, Singapore 575722. Tel: 64534730 Fax: 64571931 E-mail: enquiry@sh-motor.com

Cn. Reg. No.: 188704222K GST Reg. No.: M2-0076269-0