



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 5427D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	COVER,REAR BUMPER	BUCKLED / CUT	442.60	442.60
1	GUARD,REAR BUMPER,CENTER	BENT	576.30	576.30
1	COVER,REAR BUMPER,LOWER	SERVICEABLE	15.40	-
1	FILLER,REAR BUMPER EXTENSION,LH	SERVICEABLE	123.70	-
1	REINFORCEMENT SUB-ASSY,REAR BUMPER	BENT	332.70	332.70
1	RETAINER,REAR BUMPER SIDE,LH	SERVICEABLE	116.50	-
1	COVER,FLOOR UNDER NO.2 (RH)	SERVICEABLE	241.90	-
1	COVER,FLOOR UNDER NO.1 (LH)	SERVICEABLE	175.10	-
1	COVER,REAR FLOOR (CTR)	SERVICEABLE	229.90	-
1	COVER,DECK TRIM,REAR	SERVICEABLE	126.70	-
1	PANEL SUB-ASSY,BODY LOWER BACK	TO REPAIR SEE LABOUR	650.30	-
	LESS 25% DISCOUNT		-757.78	-337.90
			2,273.32	1,013.70
	<u>SPECIAL NETT ITEMS</u>			
1	PARKING AID (SN)	SERVICEABLE	700.00	-
1	REAR FLOOR COVER CLIP (SN)	NOT NECESSARY	60.00	-
1	REAR LOWER BUMPER CLIP (SN)	NOT NECESSARY	65.00	-
1	REAR BUMPER CLIP (SN)	NECESSARY	60.00	50.00
			885.00	50.00
	<u>LABOUR</u>			
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY,BODY LOWER BACK.		1,400.00	200.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,400.00	440.00
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.	NOT NECESSARY	240.00	-

Report Ref No. CS/AGI21010376/Kqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	10.00
			3,590.00	650.00
GRAND TOTAL			6,748.32	1,713.70
RECOMMENDED COST OF REPAIRS				1,713.70

Report Ref No. CS/AGI21010376/Kqf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.