

ASSIGNMENT

From:

Date:

Veh No:

Yr Regn:

Estimated Cost:

Type: *M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /*

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

Make:

at Workshop m/s

Colour:

of

Sp. Reading

Insured:

Eng/No:

Policy No.

C/No:

Claims No.

Gen. Cond: *Good / Fair / Poor / Burnt*

Sum Insured:

Excess:

Steering: *In order / Jammed / Leaked / Burnt or*

(Client's Record)

Brake: *In order / Jammed / Leaked / Burnt or*

Make of Veh:

Modi: *Nil / S/Rim / STD A/Rim or*

Tyre Size:

F:

R:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

SKC 56345 Yr Regn: *24/12/21*
 Type: *M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /*

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: *Good / Fair / Poor / Burnt*Steering: *In order / Jammed / Leaked / Burnt or*Brake: *In order / Jammed / Leaked / Burnt or*Modi: *Nil / S/Rim / STD A/Rim or*

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: *Frt / Rear / O/S / N/S / U/C / Rooftop or*

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

)

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

25/11/21 confirmed P/P \$5744.80 with Ben

RED: 7160.4;55%



TRANS EUROKARS PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS

EUROKARS SERVICES

ERGO Insurance Pte. Ltd. 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 ATTN : FAX :		NAME : ADDRESS : TEL :		WIP : 61501 EXCESS : DATE: 25-Aug-21	
MOTOR CLAIMS		TEL :		25-Aug-21	
VEH NO :	SKC5634S	DATE IN :		CONTACT PERSON :	RONALD
CHASSIS NO :	JM6BP2SAAM1107036	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	M3 M-HYBRID	DATE REG.:	24-Feb-21	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO	DESCRIPTION	QTY	1st	Supp	PARTS NO	REVISED	PRICES
1	REAR BUMPER	1			MBCKA-50-221ABB	DD	\$ 997.40
2	BRACKET CENTER REAR BUMPER	1			MKD53-50-251	PA	\$ 5.40
3	REINF.,REAR BUMPER	1			MBCJH-50-260	PA	\$ 541.70
4	RETAINER RH REAR	1			MBCKA-50-2H1	11	\$ 33.20
5	RETAINER LH REAR	1			MBCKA-50-2J1	11	\$ 33.20
6	GROMMET,SCREW	4			MBHN1-50-0Z1A	neu	\$ 10.80
7	PLATE SET RR BUMPER	1			MBCKA-50-2COA	PA	\$ 213.80
8	STAY,RR BUMPER	1			MBCKA-50-290	PA	\$ 91.90
9	COVER,UNDE	1			MBCKA-50-C51C	11	\$ 63.20
10	FASTENER	8			MB45A-56-146A	neu	\$ 24.00
11	TAPE,PROTECTOR	3			MBCKA-50-EM1	neu	\$ 14.10
12	BRACKET B/SENSOR BP	2			MB0J8-67-UC6	neu	\$ 46.80
13	RETAINER S.S ULTRASONIC	1			MB0L8-67-UC5	neu	\$ 25.10
14	RETAINER S.S ULTRASONIC	1			MB0L9-67-UC5	neu	\$ 25.10
15	RETAINER S.S ULTRASONIC	1			MB0M1-67-UC5	neu	\$ 25.10
16	RETAINER S.S ULTRASONIC	1			MB0M2-67-UC5	neu	\$ 25.10
17	RETAINER S.S ULTRASONIC	1			MB0J5-67-UC5 51	neu	\$ 61.30
18	RETAINER S.S ULTRASONIC	1			MB0J6-67-UC5 51	neu	\$ 61.30
19	SENSOR FRT BUMPER BP	2			MB0J8-67-UC1 51	11	\$ 380.00
20	LAMP, LICENSE	2			MB0J8-51-26Y	11	\$ 230.00
21	CAMERA BACK MONITOR	1			MB0J8-67-RCOA	SDC	\$ 1,066.80
22	TRUNK LID	1			MBCY0-52-61XA	DD	\$ 896.00
23	WEATHERSTRIP TRK LID	1			MBCJH-56-95XA	11	\$ 84.70
24	COVER,HOLE	3			MD24H-62-866	neu	\$ 7.50
25	HINGE LH TRUNK LID	1			MBCJH-52-720	11	\$ 185.10
26	HINGE RH TRUNK LID	1			MBCJH-52-710	11	\$ 185.10
27	GASKET,LAMP-LIFT GATE	2			MBCJH-51-3H8	neu	\$ 39.60
28	FASTENER	2			MEG21-51-146	neu	\$ 12.40
29	GROMMET,SCREW-R.COMB	6			MGA7B-51-146	neu	\$ 19.80
30	ORNAMENT MAZDA 3	1			MBCJH-51-721	NAC	\$ 34.60

31	ORNAMENT SKYACTIV	1			MBCJH-51-771A	net	\$	42.50
32	MAŞCOT,REAR	1			MBCJL-51-730B	net	\$	326.30
33	EMBLEM M-HYBRID	1			M11-M-HYBRID	net	\$	36.70
							TOTAL PARTS	\$ 5,845.60
							TOTAL PARTS COST	\$ 5,845.60

SUPPLEMENTARY

NO	DESCRIPTION	QTY	1st	Supp	PARTS NO	REVISED	PRICES
1	UKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company						
2							
3							
					TOTAL PARTS		\$ -
					TOTAL PARTS COST		\$ -
	Acknowledged by Repairer						
	Signature:						

Labour Description

			REVISED	PRICES
1	TO REPLACE REAR BUMPER AND TRUNK LID. TO REPAIR REAR END PANEL	660	1320	\$ 2,640.00
2	TO RESPRAY REAR BUMPER,REAR REINFORCEMENT,TRUNK LID AND REAR END PANEL	820	1260	\$ 3,150.00
3	MZ-BR-REVSEN TO TRANSFER REVERSE SENSORS.		180	\$ 330.00
4	MZ-BR-CAMERA TO TRANSFER REVERSE CAMERA.		180	\$ 330.00
5	MZ-BR-PLATE1 TO SUPPLY NUMBER PLATE.	one	NETT	\$ 70.00
6	MZ-BR-ELECTR TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		120	\$ 200.00
7	MZ-BR-REPROG TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		150	\$ 250.00
8	MZ-BR-SUNDRI SUNDRIES.	net	20	\$ 50.00

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TOTAL LABOUR	\$ -	\$ 7,020.00
TOTAL PARTS	\$ -	\$ 5,845.60
TOTAL	\$ -	\$ 12,865.60
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	\$ 12,865.60
GST 7%	\$ -	\$ 900.59
GRAND TOTAL	\$ -	\$ 13,766.19

SUPPLEMENTARY LABOUR DESCRIPTION

			REVISED	PRICES
--	--	--	---------	--------

p-2444-8

12905.20

1		#N/A		
2		#N/A		
REMARKS: THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.			TOTAL LABOUR	\$ - \$ -
			TOTAL PARTS	\$ - \$ -
			TOTAL	\$ - \$ -
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ -
			GST 7%	\$ - \$ -
			GRAND TOTAL	\$ - \$ -

TRANS EUROKARS PTE LTD

 Authorised Signature

31	ORNAMENT SKYACTIV	1			MBCJH-51-771A	\$ 42.50	\$ 42.50
32	MASCOT, REAR	1			MBCJL-51-730B		\$ 326.30
33	EMBLEM M-HYBRID	1			M11-M-HYBRID	\$ 36.70	\$ 36.70
TOTAL PARTS						\$ 2,405.20	\$ 5,845.60
TOTAL PARTS COST						\$ 2,405.20	\$ 5,845.60

SUPPLEMENTARY

NO	DESCRIPTION	QTY	1st	Supp	PARTS NO	REVISED	PRICES
1	FASTENER <i>ADD</i>	11			MBP4K-58-762 <i>new</i>	\$ 39.60	\$ 39.60
2							
3							
TOTAL PARTS							\$ 39.60 \$ 39.60
TOTAL PARTS COST							\$ 39.60 \$ 39.60

Labour Description

		REVISED	PRICES
1	TO REPLACE REAR BUMPER AND TRUNK LID. TO REPAIR REAR END PANEL.	\$ 1,320.00	\$ 2,640.00
2	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, TRUNK LID AND REAR END PANEL.	\$ 1,260.00	\$ 3,150.00
3	MZ-BR-REVSER TO TRANSFER REVERSE SENSORS.	\$ 180.00	\$ 330.00
4	MZ-BR-CAMERA TO TRANSFER REVERSE CAMERA.	\$ 180.00	\$ 330.00
5	MZ-BR-PLATE1 TO SUPPLY NUMBER PLATE	\$ 70.00	\$ 70.00
6	MZ-BR-ELECTR TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	\$ 120.00	\$ 200.00
7	MZ-BR-REPROG TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 150.00	\$ 250.00
8	MZ-BR-SUNDRI SUNDRIES.	\$ 20.00	\$ 50.00

REMARKS

4 Repair Days

TOTAL LABOUR	\$ 3,300.00	\$ 7,020.00
TOTAL PARTS	\$ 2,444.80	\$ 5,845.60
TOTAL	\$ 5,744.80	\$ 12,865.60
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ 5,744.80	\$ 12,865.60
GST 7%	\$ 402.14	\$ 900.59
GRAND TOTAL	\$ 6,146.94	\$ 13,766.19

SUPPLEMENTARY LABOUR DESCRIPTION

	REVISED	PRICES
--	---------	--------



TRANS EUROKARS PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS

EUROKARS SERVICES

ERGO Insurance Pte. Ltd. 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 ATTN. : MOTOR CLAIMS FAX :		NAME : ADDRESS : TEL :		WIP : 61501 EXCESS : DATE : 25-Aug-21			
VEH NO :	SKC5634S	DATE IN :		CONTACT PERSON :	RONALD		
CHASSIS NO :	JM6BP2SAAM1107036	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM		
MODEL :	M3 M-HYBRID	DATE REG. :	24-Feb-21	POLICY NO. :			
NATURE OF WORKS							
Parts Description							
NO	DESCRIPTION	QTY	1st	Supp	PARTS NO	REVISED	PRICES
1	REAR BUMPER	1			MBCKA-50-221ABB	\$ 997.40	\$ 997.40
2	BRACKET CENTER REAR BUMPER	1			MKD53-50-251		\$ 5.40
3	REINF.,REAR BUMPER	1			MBCH-50-260		\$ 541.70
4	RETAAINER RH REAR	1			MBCKA-50-2H1		\$ 33.20
5	RETAINER LH REAR	1			MBCKA-50-2J1		\$ 33.20
6	GROMMET,SCREW	4			MBHN1-50-021A	\$ 10.80	\$ 10.80
7	PLATE SET RR BUMPER	1			MBCKA-50-2COA		\$ 213.80
8	STAY,RR BUMPER	1			MBCKA-50-290		\$ 91.90
9	COVER,UNDE	1			MBCKA-50-C51C		\$ 63.20
10	FASTENER	8			MB45A-56-146A	\$ 24.00	\$ 24.00
11	TAPE,PROTECTOR	3			MBCKA-50-EM1	\$ 14.10	\$ 14.10
12	BRACKET B/SENSOR BP	2			MB0J8-67-UC6	\$ 46.80	\$ 46.80
13	RETAINER S.S ULTRASONIC	1			MB0L8-67-UC5	\$ 25.10	\$ 25.10
14	RETAINER S.S ULTRASONIC	1			MB0L9-67-UC5	\$ 25.10	\$ 25.10
15	RETAINER S.S ULTRASONIC	1			MB0M1-67-UC5	\$ 25.10	\$ 25.10
16	RETAINER S.S ULTRASONIC	1			MB0M2-67-UC5	\$ 25.10	\$ 25.10
17	RETAINER S.S ULTRASONIC	1			MB0J5-67-UC5 51	\$ 61.30	\$ 61.30
18	RETAINER S.S ULTRASONIC	1			MB0J6-67-UC5 51	\$ 61.30	\$ 61.30
19	SENSOR FRNT BUMPER BP	2			MB0J8-67-UC1 51		\$ 380.00
20	LAMP, LICENSE	2			MB0J8-51-26Y		\$ 230.00
21	CAMERA BACK MONITOR	1			MB0J8-67-RCOA		\$ 1,066.80
22	TRUNK LID	1			MBCY0-52-61XA	\$ 896.00	\$ 896.00
23	WEATHERSTRIP TRK LID	1			MBCH-56-95XA		\$ 84.70
24	COVER,HOLE	3			MD24H-62-866	\$ 7.50	\$ 7.50
25	HINGE LH TRUNK LID	1			MBCH-52-720		\$ 185.10
26	HINGE RH TRUNK LID	1			MBCH-52-710		\$ 185.10
27	GASKET,LAMP-LIFT GATE	2			MBCH-51-3H8	\$ 39.60	\$ 39.60
28	FASTENER	2			MEG21-51-146	\$ 12.40	\$ 12.40
29	GROMMET,SCREW-R.COMB	6			MGA7B-51-146	\$ 19.80	\$ 19.80
30	ORNAMENT MAZDA 3	1			MBCH-51-721	\$ 34.60	\$ 34.60