

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 11 Oct 2021

Preliminary Advice

Insured Vehicle No	: YQ436R		
TP Vehicle No	: GBJ9285J	Accident Date	: 06/10/2021
Make	: MITSUBISHI CANTER	Assignment Date	: 08/10/2021
Date of Inspection	: 08/10/2021	Est. Duration of Repair	: 5
Inspection At	: LIU'S BROTHER AUTO WORKSHOP (HQ) 1 KAKI BUKIT AVE 6 #01-01, AUTO BAY@KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,923.80
Revised Amount	:S\$	7,874.53
Check Items (Estimated)	:S\$	0.00
Total	:S\$	7,874.53

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :Please note that the preliminary advice amount (Revised) stated are subject to consistency check, part prices and labour cost.