

Our Job Ref No 305489780

Date 14/10/2021

ENGINEERING

ComfortDeGro Engineering Pte Ltd
59 Loyang Drive Singapore 508989
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : THEVAN

: SHA1012J

DOA: 06/10/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


1. The repair job shall bill to: ECICS --- SJW4213L
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost
 - (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$9,700.00
Final Lumpsum Repair cost
3. Estimated normal period for repairs: 5 working days
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature : 

Name : JUMANI

Tel : 6214 8315

Fax : 65468156

Signature : 

Name : THEVAN

Date : 15/10/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	7.49 / 2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

SUPPLEMENTARY OF PARTS AND LABOUR COSTS			
DESCRIPTION	QTY	ESTIMATE	REMARKS
EXHAUST PIPE RH		\$1,935.40	LIST ✓ BT
EXHAUST PIPE CENTRE		\$730.10	LIST ✓ BT
CHECK ITEM			
LABOUR			
RENEW EXHAUST PIPE ASSY		\$120.00	✓
TOTAL:		\$2,785.50	JUMANI

REPAIR ESTIMATE*

DATE:

MVA JUMANI

DOA: 6. Oct. 2021

ECICS

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	BOOTLID COVER			\$2,609.80
	BOOTLID HINGE LH			\$142.30
	BOOTLID HINGE RH			\$142.30
	BOOTLID LOCK			\$114.90
	BOOTLID EMBLEM - H			\$63.10
	BOOTLID EMBLEM - CRDI			\$52.40
	BOOTLID EMBLEM - I40			\$67.90
	TAILLAMP ASSY RH			\$697.80
	TAILLAMP ASSY LH			\$697.80
	REAR BUMPER ASSY			\$553.00
	REAR BUMPER UNDER COVER			\$228.00
	REAR BUMPER REINFORCEMENT			\$428.40
10	REAR BUMPER CLIPS			\$22.00
	BUMPER REINFORCEMENT BRACKET LH			\$160.60
	BUMPER REINFORCEMENT BRACKET RH			\$160.60
	REAR BUMPER SPONGE			\$119.50
	BOOTLID MOULDING			\$85.00
	BOOTLID LOWER GARNISH			\$227.90
	BOOTLID LAMP LH			\$622.20
	BOOTLID LAMP RH			\$622.20
	REAR BUMPER REFLECTOR RH			\$32.00
	REAR END PANEL			\$526.70
	REAR END PANEL GARNISH			\$57.70
	REAR FENDER RH			\$2,171.40
	SPARE TYRE PANEL			\$852.80
	REAR BUMPER SIDE BRACKET LH			\$35.60
	SPARE TYRE LOCK NUT			\$41.80
	SUB TOTAL			\$11,535.70
	LESS 20%			\$2,307.14
	DISCOUNTED TOTAL			\$9,228.56
	REAR NUMBER PLATE			\$50.00
2	WINDSCREEN SEALANT			\$46.00
1	BOOTLID COMFORT LOGO			\$30.00
1	BOOTLID TEL. NOS LOGO			\$30.00
1	BOOTLID APPS LOGO			\$40.00
	REVERSE SENSOR			\$135.70
				\$331.70
	Labour Charge			
	PANEL BEATING			\$1,200.00
	SPRAY PAINT			\$1,000.00
	CHECK WIRING			\$50.00

