



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info |
|--|--|
| ANG YU ANN 155 GANGSA ROAD #14-335 SINGAPORE 670155 Contact No 4 days | <div> <div>Cust No/Name</div> <div>Reg No/Reg Date</div> <div>Date In/Mileage</div> <div>Chassis No</div> <div>Engine No</div> <div>Make/Model</div> <div>Colour/Trim</div> </div> <div> <div>LCV14576/ANG YU ANN</div> <div>SNC1674S / 30/09/202</div> <div>08/10/2021/ 0</div> <div>KNAD6817VN6611137</div> <div>G3LFMP173906</div> <div>KIA/STONIC 1.0 A PE SX EJQ</div> <div>4SS SILKY SILVER / WK SATURN BLACK</div> </div> |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | | |
|--|------------------------------|-------------------|------|-------------------|------------|-------|------------|
| LCV14576 | CRDVCH | 08/10/2021/ 15:10 | QUK | 282 / Kevin Leong | 40787 | | |
| Description of Goods / Services | | | | Qty | Unit Price | Disc% | Amount |
| E PNT88000 REPLACE FRT BUMPER & AFFECTED AREA 400X1 | | | | | | | 400 800.00 |
| E PNT98000 PAINT WORK ON FRT BUMPER PANEL & BONNET 350X2 | | | | | | | 700.00 |
| E PNT88000 REMOVE & INSTALL FRT PARKING ASSIST FOR FACILITATE REPAIR | | | | | | | 60 120.00 |
| A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM | | | | | | | 30.00 |
| A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM | | | | | | | 120.00 |
| M SUNDRY TO SUPPLY FRT NUMBER PLATE WITH FRAME | | | | | | | 50.00 |
| M SUNDRY SUNDRIES | | | | | | | 20 50.00 |
| E PNT88000 REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR | | | | | | | 120.00 |
| M SUNDRY TO TOP UP AIRCON GAS | | | | | | | 80.00 |
| M | COVER-FR BUMPER | BR | 1.00 | 295.00 | 00.00 | | 295.00 |
| M | GRILLE ASSY-RADIATOR | CUT | 1.00 | 324.00 | 00.00 | | 324.00 |
| M | COVER-FR BUMPER, LWR | CUT | 1.00 | 367.00 | 00.00 | | 367.00 |
| M | SKID PLATE-FR BUMPER | CRW | 1.00 | 55.00 | 00.00 | | 55.00 |
| M | GRILLE-FRONT BUMPER | BR | 1.00 | 247.00 | 00.00 | | 247.00 |
| M | STRIP-FR BUMPER | x nn | 1.00 | 27.00 | 00.00 | | 27.00 |
| M | ABSORBER-FRONT BUMPER ENERGY | BR | 1.00 | 98.00 | 00.00 | | 98.00 |
| M | STIFFNER-FR BPR LWR | BR | 1.00 | 123.00 | 00.00 | | 123.00 |
| M | WIRING HARNESS-FR BUMPER | x nn | 1.00 | 150.00 | 00.00 | | 150.00 |
| M | CONDENSER ASSY-COOLER | nn (photo) | 1.00 | 648.00 | 00.00 | | 648.00 |
| M | AIR GUIDE | x nn | 1.00 | 52.00 | 00.00 | | 52.00 |
| M | RADIATOR ASSY | x nn | 1.00 | 696.00 | 00.00 | | 696.00 |
| M | COOLER ASSY-INTER | x nn | 1.00 | 564.00 | 00.00 | | 564.00 |
| M | ULTRASONIC SENSOR ASSY-P.A.S | BR | 1.00 | 177.00 | 00.00 | | 177.00 |

Confirm & accepted by

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

7% GST on **5893.00** **412.51**

Nett **5,893.00**

Total Payable **6,305.51**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.