

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: ~~M~~ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ~~W~~order / Jammed / Leaked / Burnt orBrake: ~~W~~order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / ~~MIC~~ OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Corr. unli. 28-02-2022 174571563

park and found case TP owner went replaced new bumper

27/1/12 \$ 6785 informed hailer

Date/Time, File Pass to?

☐

Preli. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) \$ + RS. \$1

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLJ9800D/2110088

09th October 2021

The Manager

Motor Claim Department

AIG Asia Pacific Insurance Pte Ltd

CHARTIS Building

78 Shenton Way #07-16

Singapore 079120

Click Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date of Accident

: 09th October 2021

Location

: Kaki Bukit Road 1

Third Party Claim Vehicle No

: GBJ 7305 Z

Repair Cost For Vehicle No

: SLJ 9800 D Porsche 911 Carrera

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Front bumper fascia	1 set	3,550.00	\$ 3,550.00 ✓
2	Front bumper clips	1 set	100.00	\$ 100.00 ✓
3	Front bumper sensor (centre)	2	407.00	\$ 814.00 ✓
4	Front bumper sensor gasket	2	15.00	\$ 30.00 ✓
5	Front bumper signal lamp RH	1	180.00	\$ 180.00 ✓
6	Front bonnet emblem (logo)	1	400.00	\$ 400.00 ✓
7	Front number plate (s/nett)	1	100.00	\$ 100.00 ✓
				\$ 5,174.00

Labour Charges :-

	Amounts
Cut out, renew, knocking & welding front bonnet, remove & install all damage parts, straighten & re-align body	\$ 1,080.00 750
Spray painting on damage parts	\$ 1,200.00 700
Remove & refix front bumper sensor	\$ 100.00 50
Check all lighting after repairs	\$ 80.00 20
Body sticker on damage parts (XPEL ULTIMATE PLUS PPF)	\$ 1900.00 ✓
Diagnostic check & reset	\$ 380.00 80

Labour Charge

Total Amount

GST will be reflected in the final bills.

p - 3650
10%

3285

678

Notes :- Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.



TAX INVOICE

Billed To

SPECIALISTS MOTOR PTE LTD
BLOCK 3018A, UBI ROAD 1
#01-24/25/26
(S)408711
ATTN:KAREN

Invoice Number

RC56205

Invoice Date

16/12/2021

S/N	Description	Qty	Unit Price	Amount
1	PORSCHE 911--SU9800D--CHASSIS:112019--FRONT HOOD -XPEL ULTIMATE PLUS PPF	1	1,000.00	1,000.00
2	PORSCHE 911--SU9800D--CHASSIS:112019--FRONT BUMPER -XPEL ULTIMATE PLUS PPF	1	900.00	900.00

Bank Account Details

Company Name : Rikecool Automotive Film Pte Ltd
Bank Name : DBS Bank
Bank A/C No. : 008-900595-2
PAYNOW : UEN-200504253G

Subtotal 1,900.00

GST 7% 133.00

Total (Incl. GST) 2,033.00

Accounts Receivable Team



AUTHORISED SIGNATURE**RIKECOOL AUTOMOTIVE FILM PTE LTD**

50 Ubi Ave 3 #03-02 Frontier Epark @ Ubi Singapore 408866

Company Registration No: 200504253G GST Registration No: 20-0504253-G

Tel. +65 6297 2422 Fax. +65 6294 2522 Email: rikecool@singnet.com.sg